



WALL AND CEILING IN CRITICALLY POOR CONDITION
 structure of gutter plate and detailed arrangement
 of bearing ends of rafters not possible to discern

REAR HALF OF ATTIC
 NOT ACCESSIBLE FOR SURVEY
 structure of wall plate and
 detail of bearing ends of rafters
 not possible to discern

FOUL WASTE ROUTE NOT KNOWN BELOW TOP FLOOR

ROUTE NOT KNOWN

ASSUMED ROUTE - PIPE SEEN AT BASE OF BOX

EXISTING SECTION



Bridget Sheppard Architect



T: +44 (0)20 8498 0211
 W: bridgetsheppard.com
 E: bridget.sheppard@btinternet.com

1A Bramley Close
 Woodford Green
 Essex. IG8 7PL

CLIENT Venoru Ltd	
PROJECT 49 Marchmont Street, WC1N 2AN	
DRAWING EXISTING SECTION	
DRG. No 09	REVISION A
SCALE 1:50 @ A3 PAPER	DATE 16 Jan 2018