









Appendix G

Photographic Schedule

	
1. Front Elevation College Building	2. Front Elevation Area
	
3. Front Elevation, 3 External Entrance Doors Open	4. Inside Existing Entrance Lobby Looking Outwards, Original Doors Fixed Open



Appendix G (continued) Photographic Schedule

	
<p>5. Existing Entrance Lobby Matting System</p>	<p>6. Ceiling Area As Existing Within Lobby</p>
	
<p>7. Threshold to Entrance Door Through to Lobby</p>	<p>8. Original Timber Panelled External Door</p>



Appendix G (continued) Photographic Schedule



9. Original Panelled Entrance Door In Shut Position



10. Entrance Lobby Double Doors Used for Escape Purposes Only







11. View Into Existing Entrance Lobby Through Double Doors



12. Existing Inbuilt Cupboards with Pine Clad Panels RHS Area As Enter Building







Appendix G (continued) Photographic Schedule

	
<p>13. Doors and Door Head Finished In Pine Cladding to LHS Area as Enter Reception Area</p>	<p>14. Existing Reception Desk, Structural Columns Behind With Oversized GRP Cladding</p>
	
<p>15. Existing Ceiling With Surface Mounted Fixtures</p>	<p>16. View from RHS Area of Reception as Enter Looking Across Reception Area. Existing Carpet Finish and Grey Vinyl Shown</p>




Appendix G (continued) Photographic Schedule

	
<p>17. Existing Metal Venetian Blinds Fitted to Window Reveal</p>	<p>18. View Into Existing Suspended Ceiling Void</p>
	
<p>19. Abutment Detail of Existing Curtain Walling to Wall</p>	<p>20. Existing Soffit to Structural Ceiling Above Suspended Ceiling. Structure Appears to be Hollow Clay Pot and Beam Construction, Underside Plastered and Painted Black</p>



Appendix G (continued) Photographic Schedule

	
<p>21. Underside of Existing Floor Covering, Screed Finish</p>	