

Parts to be stripped out. Any brickwork and roof tiles to be

salvaged where possible

Operatives:

clear of mud and debris.

clean-up regimes.


course of the Works. Partly Demolished Structures:

Dangerous Openings:

Asbestos Containing Materials

Site Condition at Completion:

Soil infill within crawl space to be removed



Chimney stack to be re-built as per Structural Engineer's recommendation. Brickwork to be carefully removed and re-used. Any damaged bricks and

Condition of roof to be inspected. Any damaged tiles to be replaced to

match existing. Roof tiles to be cleaned using a water based system, no

Paint to door to be stripped back, substrate to be made good and prepared

to receive new paint application. All detailing to door reveal to be retained,

refurbished and protected throughout the construction programme.

chemical clean permitted. Any defects to be reported to architect.

chimney pots to be replaced to match existing.

