

Entrance Hall - North elevation showing the main entrance door and surrounding framework.




Entrance Hall - showing the full height ceiling and cornice detailing.



Entrance Hall - West elevation showing the existing bathroom door.



Entrance door - showing the door style of the existing original doors .






Bathroom - West elevation showing the current layout of the existing fittings




Bathroom - Detail showing the access panel for the plumbing and electrical services.



Bathroom - South elevation showing the bath /shower.



Bathroom - East elevation showing the door through to the entrance hall.





facade windows.




Room 1 - showing the west elevation.




Room 1 - showing the East elevation with the currently installed only fixed lighting provision in the room .



Room 1 - showing the doorway to the entrance hall with the threshold transition between the carpeted chipboard and the original softwood flooring.



Room 1 - showing one of the skirting mounted socket boxes and the skirting profile.





Room 2 - South elevation showing the original facade windows.




Room 2 - North elevation showing the position of cupboard housing the electrics.



Room 2 - East elevation showing the original stone fire surround and passage to room 3.




Room 2 - West elevation



Room 2 - North elevation showing the door through to the entrance hall.




Room 2 - MDF cupboardcurrently installed to house the electrical provision for the apartment.



Apartment 2.02 St Pancras Chambers - Room 2



Room 3 - West elevation



Room 3 - South elevation



Room 3 - East elevation




Room 3 - North elevation showing the side sub-walls to house the kitchen services



Room 3 - Kitchen detail showing the access port to the wall cavity housing building services.



Room 3 - Plaster skirting detail .






Detail showing the bare floor finish exposed by the removal of a piece of new fitted furniture, contrasted with the adjascent polyurethane varnish finish.



Detail showing the mastic used around the board covering the fireplace in Room 2



Detail showing the gaps and mastic between the floor and the skirting



Detail showing the gaps present



Detail showing the general marking and scuffing and nail holes



Detail of the flooring around the fireplace

Apartment 2.02 St Pancras Chambers - Flooring details