


1 Existing white painted render
2 Existing London stock brickwork
3 Existing brickwork
4 Existing lead roof
5 Modern lead roof (existing)
6 Modern brickwork repair (existing)
7 / 13 Existing timber windows
8 Existing slate roof
9 Existing level access from Bedford Plc
11 Existing raillings
14 Existing asphalt roof
16 Existing window opening bricked up



Acrylic _ window guard Office 3710 1330 3680 Teaching wall Classroom \bigcirc Acrylic window guard

4

(%)

Drylining behind teaching wall 6

New dado rail and skirting

Teaching wall

Group Room

Reception

3530

(NG-12)

Screen glass and concealed door in line with top of existing double doors

Acrylic window guard

RUSSELL SQUARE

 \bigcirc

(E)

3580


2500

Medical Room

Teaching wall

L____Acrylic_ window guard

3.0



!Health and Safety Note:
R+D Asbestos survey to be undetaken before commencing any works.

Refer also to:
-DDT Architects drawings for fitout layout details,
-Schedule of works
-Mechanical and Electrical design drawings.

A R C H I T E C T S

135-139 Curtain Road London EC2A 3BX T: +44 (0)20 7841 7200 E: info@ewa.co.uk 52-53 Russell Square - Phase 1
Proposed Section A
AG(06)01
STATUS | PLANNING
DRAWN BY | EWA