



## 2018/1696/P Representations – Annex

The built staircase.



The two flights are 6 and 11 steps instead of 9 and 9. The finish is uncoated galvanised steel. Safety rods not in evidence.



Illustrating the degree to which the staircase, when extended, will dominate the view from the maisonettes.



“Industrial” finish (or unfinished?)

Does anyone really want another four flights plus a landing that looks like this??

### **Staircase – State of Completion/Poor Standard**

Streaking and stalactites caused by leaching.





Unboxed cables, unlagged pipes, unprotected wood.



## Cycle Store – Unfinished and Unsafe

Hole in the floor, unboxed high voltage cables hanging on screws.



Unpainted, racking not screwed to wall.



## Refuse Store Capacity

Where the office's refuse store should be, according to the plans.



Commercial waste sometimes requires significant space. Black sacks on floor because office doesn't have a refuse bin of its own.





Residential waste already seems close to capacity on occasion.

