



General Tree Assessment (Detailed)

Tree Condition Survey 2018

Tree ID: 1 Silver Maple **Tag: 612** **Assessor:** Maria Diez-Alonso
Acer saccharinum **TPO:** **Date:** 23-May-18

Survey Comment: Reduce crown to previous pruning points (by approx. 4-5m in height and 3m in spread). Some lateral branches have not been reduced in the past, reduce accordingly as explained before. Remove epicormic growth up to crown break. Remove major dead wood. Damage on buttresses facing south and west. TM required.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	18 m	5 m	1	540 mm	Semi-mature	No		N/A	23-Nov-19	Fair
Observations	Root				Stem			Branch	Leaf/Bud	
	Damage to buttress roots				Old pruning wounds Epicormic growths			Minor dead wood Major dead wood Pollard	Normal	
Work	Category				Action				Priority	
	See Comment				See Comment				6 Months	

General Tree Assessment (Detailed)

Tree ID: 2 London Plane *Platanus x hispanica* **Tag:** 424 **Assessor:** Maria Diez-Alonso
TPO: **Date:** 23-May-18

Survey Comment: Cavity at 4m (20cm width and 30cm height) - climb, inspect and record condition and depth. Remove epicormic growths near cavity. Stress marks on lower side on limb facing south-west - climb, inspect and record if the damage is not superficial and there are bark wounds or splits. Road side lifted due to root expansion. Tree has been reduced in the past (heavier reduction on road side). Further works might be required after inspections.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	25 m	10 m	1	1330 mm	Mature			N/A	23-Nov-19	Good
Observations	Root		Stem			Branch		Leaf/Bud		
	No visual defects		Old pruning wounds Cavities Epicormic growths			Damage / wounding Minor dead wood Old pruning wounds		Normal		
Work	Category		Action			Priority				
	Further inspection		Climb and inspect Massaria inspection			3 Months 3 Months				
	Reduce crown(s)		To previous pruning points			3 Years				
	Remove		Epicormic growths			3 Months				

Tree ID: 3 Sycamore *Acer pseudoplatanus* **Tag:** 425 **Assessor:** Maria Diez-Alonso
TPO: **Date:** 23-May-18

Survey Comment: Tree has been reduced on road side.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	14 m	5 m	1	600 mm	Mature			N/A	23-Nov-19	Good
Observations	Root		Stem			Branch		Leaf/Bud		
	No visual defects		Old pruning wounds Epicormic growths			Damage / wounding Minor dead wood Major dead wood		Normal		
Work	Category		Action			Priority				
	No action		No action							

General Tree Assessment (Detailed)

Tree ID: 4

Small-Leafed Lime
Tilia cordata

Tag:

TPO:

Assessor: Maria Diez-Alonso

Date: 23-May-18

Survey Comment: Prune back by approx. 3m over tennis court. Minor cavity at 2m.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	15 m	7 m	1	570 mm	Mature	No		N/A	23-Nov-19	Good
Observations	Root	Stem			Branch			Leaf/Bud		
	Damage to buttress roots	Leaning Old pruning wounds Cavities Trifurcated			Minor dead wood Major dead wood Old pruning wounds			Normal		
Work	Category	Action			Priority					
	Prune	Unspecified			1 year					
	Remove	Major dead wood			3 Months					

Tree ID: 5

London Plane
Platanus x hispanica

Tag: 616

TPO:

Assessor: Maria Diez-Alonso

Date: 23-May-18

Survey Comment: TM and parking suspension required. Bark wound on lower side of limb facing north- probably stress mark due to fair shape of limb. Similar marks on limb facing south at 15m. Climb, inspect and record if the damage is not superficial and there are bark wounds or splits.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	20 m	11 m	1	1150 mm	Mature			N/A	23-Nov-19	Good
Observations	Root	Stem			Branch			Leaf/Bud		
	No visual defects	Old pruning wounds Epicormic growths			Damage / wounding Minor dead wood Major dead wood Old pruning wounds Epicormic growths			Normal		
Work	Category	Action			Priority					
	Further inspection	Climb and inspect			3 Months					
		Massaria inspection			3 Months					
	Remove	Major dead wood			3 Months					

General Tree Assessment (Detailed)

Tree ID: 6 London Plane *Platanus x hispanica* **Tag:** 428 **Assessor:** Maria Diez-Alonso
TPO: **Date:** 23-May-18

Survey Comment: Bark wounds/stress barks on lower side of limb over road -climb, inspect and record if the damage is not superficial and there are bark wounds or splits. Large dead branches. TM and parking suspension.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	27 m	10 m	1	1600 mm	Mature			N/A	23-Nov-19	Good
Observations	Root		Stem		Branch			Leaf/Bud		
	No visual defects		Old pruning wounds Trifurcated		Damage / wounding Minor dead wood Major dead wood Old pruning wounds Epicormic growths			Normal		
Work	Category		Action				Priority			
	Further inspection		Climb and inspect Massaria inspection				3 Months 3 Months			
	Remove		Major dead wood				1 Month			

Tree ID: 7 Whitebeam *Sorbus aria* **Tag:** 429 **Assessor:** Maria Diez-Alonso
TPO: **Date:** 23-May-18

Survey Comment: Bifurcated at 3m - cup shape fork (low risk of failure).

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	10 m	3 m	1	300 mm	Semi-mature	No		N/A	23-Nov-19	Good
Observations	Root		Stem		Branch			Leaf/Bud		
	No visual defects		Old pruning wounds Bifurcated		Minor dead wood Old pruning wounds			Normal		
Work	Category		Action				Priority			
	No action		No action							

General Tree Assessment (Detailed)

Tree ID: 8 Common Lime
Tilia europaea **Tag:** 430 **Assessor:** Maria Diez-Alonso
TPO: **Date:** 23-May-18

Survey Comment: Remove: basal growth, epicormic growths up to 4m from ground level, all major dead wood, minor dead wood longer than 1m. Cut back growth over tennis court to fence line (to old pruning point). Re-inspect when works completed.TM required.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	11 m	4 m	1	550 mm	Mature			N/A	23-Nov-19	Fair
Observations	Root		Stem		Branch			Leaf/Bud		
	Sucker growth		Epicormic growths		Minor dead wood Major dead wood			Normal		
Work	Category		Action		Priority					
	Re-inspect See Comment		See Comment See Comment		1 Month					

Tree ID: 9 Privet
Ligustrum Ligustrum sp. **Tag:** 431 **Assessor:** Maria Diez-Alonso
TPO: **Date:** 23-May-18

Survey Comment: Extensive bark wound.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	5 m	3 m	1	190 mm	Mature	No		N/A	23-Nov-19	Poor
Observations	Root		Stem		Branch			Leaf/Bud		
	No visual defects		Bark wounds Leaning		Minor dead wood			Normal		
Work	Category		Action		Priority					
	Fell		Fell to ground level		3 Months					

General Tree Assessment (Detailed)

Tree ID: 10 London Plane **Tag:** 0631 & 0432 **Assessor:** Maria Diez-Alonso
Platanus x hispanica **TPO:** **Date:** 23-May-18

Survey Comment: Trifurcated at 2.5m (tensile forks). Remove epicormic growth up to 5m from ground level. Tree has been recently crown reduced. TM and parking suspension.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	25 m	8 m	1	2000 mm	Mature			N/A	23-Nov-19	Good
Observations	Root		Stem		Branch		Leaf/Bud			
	No visual defects		Old pruning wounds Trifurcated		Minor dead wood Old pruning wounds Epicormic growths		Normal			
Work	Category		Action		Priority					
	Further inspection		Massaria inspection		3 Months					
	Reduce crown(s)		To previous pruning points		3 Years					
	Remove		Epicormic growths		3 Months					

Tree ID: 11 London Plane **Tag:** 622 **Assessor:** Maria Diez-Alonso
Platanus x hispanica **TPO:** **Date:** 23-May-18

Survey Comment: Raise canopy over road. TM and parking suspension. Public path lifted due to root expansion. Bifurcated at 5m (tensile fork). Bark wounds/stress marks on lower part of limb facing west at 20m - climb, inspect and record if the damage is not superficial and there are bark wounds or splits.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	27 m	11 m	1	1340 mm	Mature			N/A	23-Nov-19	Good
Observations	Root		Stem		Branch		Leaf/Bud			
	No visual defects		Bifurcated		Damage / wounding Minor dead wood Major dead wood		Normal			
Work	Category		Action		Priority					
	Further inspection		Climb and inspect Massaria inspection		3 Months 3 Months					
	Raise low canopy		To 5.5m		3 Months					
	Remove		Major dead wood		3 Months					

General Tree Assessment (Detailed)

Tree ID: 12 Wild Cherry **Tag:** 0627 & 0457
Prunus avium **TPO:** **Assessor:** Maria Diez-Alonso
Date: 23-May-18

Survey Comment: Cut back growth on tennis court side back to fence or near suitable pruning point (approx 2m). Bark wounds on 2x limbs facing east - one bark wound located on upper side of limb could not be inspected - climb, inspect and record size and condition.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	14 m	6 m	1	490 mm	Mature	No		N/A	23-Nov-19	Fair
Observations	Root	Stem			Branch			Leaf/Bud		
	No visual defects	Leaning Old pruning wounds			Damage / wounding Minor dead wood Major dead wood Old pruning wounds			Normal		
Work	Category	Action			Priority					
	Cut back growth	Unspecified			3 Months					
	Remove	Major dead wood			3 Months					

Tree ID: 13 Wild Cherry **Tag:** 625
Prunus avium **TPO:** **Assessor:** Maria Diez-Alonso
Date: 23-May-18

Survey Comment:

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	14 m	7 m	1	550 mm	Mature	No		N/A	23-Nov-19	Good
Observations	Root	Stem			Branch			Leaf/Bud		
	No visual defects	Old pruning wounds			Damage / wounding Minor dead wood Major dead wood			Normal		
Work	Category	Action			Priority					
	Remove	Major dead wood			3 Months					

General Tree Assessment (Detailed)

Tree ID: 16

Privet
Ligustrum Ligustrum sp.

Tag: 436
TPO:

Assessor: Maria Diez-Alonso
Date: 23-May-18

Survey Comment:

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	4 m	2 m	4	150 mm	Mature	No		N/A	23-Nov-19	Good
Observations	Root			Stem		Branch		Leaf/Bud		
	No visual defects			Leaning Old pruning wounds Multi stemmed		Minor dead wood		Normal		
Work	Category			Action		Priority				
	No action			No action						

Tree ID: 17

English Elm
Ulmus procera

Tag:
TPO:

Assessor: Maria Diez-Alonso
Date: 23-May-18

Survey Comment:

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	10 m	4 m	1	300 mm	Semi-mature	No		N/A	23-Nov-19	Good
Observations	Root			Stem		Branch		Leaf/Bud		
	No visual defects			Old pruning wounds Bifurcated		Minor dead wood Old pruning wounds		Normal		
Work	Category			Action		Priority				
	No action			No action						

General Tree Assessment (Detailed)

Tree ID: 20	Tree of Heaven <i>Ailanthus altissima</i>	Tag:	Assessor: Maria Diez-Alonso							
		TPO:	Date: 23-May-18							
Survey Comment: Remove all major dead wood and minor dead wood longer than 1m.										
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	14 m	6 m	1	340 mm	Mature	No		N/A	23-Nov-19	Fair
Observations	Root		Stem		Branch		Leaf/Bud			
	No visual defects		Old pruning wounds		Minor dead wood Major dead wood		25% dead / absent			
Work	Category		Action		Priority					
	Remove		Unspecified		3 Months					

Tree ID: 21	Common Lime <i>Tilia europaea</i>	Tag:	Assessor: Maria Diez-Alonso							
		TPO:	Date: 23-May-18							
Survey Comment: Bifurcated at 6m, 1x limb from this union is dead. Pollard to approx 6m (stem union) to remove major dead wood and balance canopy. Remove also sucker growth and all epicormic growths. Manage as pollard on 3-5 years pruning cycle. TM and parking suspension.										
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	10 m	3 m	1	350 mm	Semi-mature			N/A	23-Nov-19	Fair
Observations	Root		Stem		Branch		Leaf/Bud			
	Sucker growth		Leaning Epicormic growths Bifurcated		Major dead wood		25% dead / absent			
Work	Category		Action		Priority					
	See Comment		See Comment		3 Months					

General Tree Assessment (Detailed)

Tree ID: 22 Tree of Heaven
Ailanthus altissima **Tag:** **Assessor:** Maria Diez-Alonso
TPO: **Date:** 23-May-18

Survey Comment: Remove all major dead wood and minor dead wood longer than 1m. Bifurcated from 10m (tensile fork). TM required.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	15 m	5 m	1	910 mm	Mature	No		N/A	23-Nov-19	Fair
Observations	Root		Stem			Branch		Leaf/Bud		
	No visual defects		Old pruning wounds Bifurcated			Minor dead wood Major dead wood		25% dead / absent		
Work	Category		Action			Priority				
	Remove		Unspecified			3 Months				

Tree ID: 23 Privet
Ligustrum Ligustrum sp. **Tag:** **Assessor:** Maria Diez-Alonso
TPO: **Date:** 23-May-18

Survey Comment:

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	4 m	1 m	2	90 mm	Semi-mature	No		N/A	23-Nov-19	Good
Observations	Root		Stem			Branch		Leaf/Bud		
	No visual defects		Bifurcated			Damage / wounding Minor dead wood Old pruning wounds		Normal		
Work	Category		Action			Priority				
	No action		No action							

General Tree Assessment (Detailed)

Tree ID: 24	Privet <i>Ligustrum Ligustrum sp.</i>	Tag:	Assessor: Maria Diez-Alonso							
		TPO:	Date: 23-May-18							
Survey Comment:										
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	4 m	2 m	1	100 mm	Semi-mature	No		N/A	23-Nov-19	Good
Observations	Root	Stem				Branch		Leaf/Bud		
	No visual defects	Old pruning wounds				Minor dead wood		Normal		
Work	Category	Action				Priority				
	No action	No action								

Tree ID: 25	London Plane <i>Platanus x hispanica</i>	Tag:	Assessor: Maria Diez-Alonso							
		TPO:	Date: 23-May-18							
Survey Comment: Climb, inspect and record size and condition of cavities. One cavity at 10m on one of the main stems facing south. One small cavity on limb facing north. Tree has been reduced on road side. Remove regrowth from old pruning point at approx 12m over road facing west (lowest limb) -regrowth shows fair vitality, might be decay on old wound or Massaria infection. Trifurcated at 7m (tensile fork). TM and parking suspension.										
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	20 m	11 m	1	1369 mm	Mature			N/A	23-Nov-19	Good
Observations	Root	Stem				Branch		Leaf/Bud		
	No visual defects	Old pruning wounds Cavities Ivy covered Bifurcated				Damage / wounding Minor dead wood Old pruning wounds Cavities		Normal		
Work	Category	Action				Priority				
	Further inspection	Climb and inspect Massaria inspection				3 Months 3 Months				
	Ivy Remove	Sever/remove up to 1.5m from ground level See Comment				3 Months 3 Months				

General Tree Assessment (Detailed)

Tree ID: 26	Privet <i>Ligustrum Ligustrum sp.</i>	Tag: 446 TPO:	Assessor: Maria Diez-Alonso Date: 23-May-18							
Survey Comment:										
Details	Height 3 m	Spread 2 m	Stems 1	Ø 140 mm	Maturity Semi-mature	Bat No	Con Area	Prev Insp N/A	Next Due 23-Nov-19	Condition Fair
Observations	Root No visual defects	Stem Leaning Old pruning wounds		Branch Minor dead wood		Leaf/Bud Normal				
Work	Category No action	Action No action						Priority		

Tree ID: 27	London Plane <i>Platanus x hispanica</i>	Tag: 447 TPO:	Assessor: Maria Diez-Alonso Date: 23-May-18							
Survey Comment: Bifurcated at 8m (tensile fork). Bark wounds/stress marks on upper crown on limbs facing south, north and east - climb, inspect and record if the damage is not superficial and there are bark wounds or splits.										
Details	Height 20 m	Spread 11 m	Stems 1	Ø 1260 mm	Maturity Mature	Bat	Con Area	Prev Insp N/A	Next Due 23-Nov-19	Condition Good
Observations	Root No visual defects	Stem Bifurcated		Branch Damage / wounding Minor dead wood Major dead wood		Leaf/Bud Normal				
Work	Category Further inspection	Action Climb and inspect						Priority 3 Months		
		Action Climb and inspect						Priority 3 Months		
	Category Raise low canopy	Action To 5.5m						Priority 3 Months		
	Category Remove	Action Major dead wood						Priority 3 Months		

General Tree Assessment (Detailed)

Tree ID: 28	Privet <i>Ligustrum Ligustrum sp.</i>	Tag:	Assessor: Maria Diez-Alonso							
		TPO:	Date: 23-May-18							
Survey Comment:										
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	3 m	2 m	1	100 mm	Semi-mature	No		N/A	23-Nov-19	Good
Observations	Root	Stem				Branch		Leaf/Bud		
	No visual defects	Bark wounds Old pruning wounds				Minor dead wood		Normal		
Work	Category	Action				Priority				
	No action	No action								

Tree ID: 29	Crab Apple <i>Malus sylvestris</i>	Tag: 605	Assessor: Maria Diez-Alonso							
		TPO:	Date: 23-May-18							
Survey Comment:										
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	5 m	4 m	1	200 mm	Semi-mature	No		N/A	23-Nov-19	Good
Observations	Root	Stem				Branch		Leaf/Bud		
	No visual defects	Old pruning wounds				Minor dead wood Old pruning wounds		Normal		
Work	Category	Action				Priority				
	No action	No action								

General Tree Assessment (Detailed)

Tree ID: 30 London Plane
Platanus x hispanica **Tag:** **Assessor:** Maria Diez-Alonso
TPO: **Date:** 23-May-18

Survey Comment: Tree has been reduced on road side. Stress marks on limbs on lower parts of limbs upper crown - climb, inspect and record if the damage is not superficial and there are bark wounds or splits.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	20 m	11 m	1	1030 mm	Mature			N/A	23-Nov-19	Good
Observations	Root		Stem		Branch			Leaf/Bud		
	No visual defects		Trifurcated		Damage / wounding Minor dead wood Old pruning wounds			Normal		
Work	Category		Action		Priority					
	Further inspection		Climb and inspect Massaria inspection		3 Months 3 Months					

Tree ID: 31 Crab Apple
Malus sylvestris **Tag:** 452 **Assessor:** Maria Diez-Alonso
TPO: **Date:** 23-May-18

Survey Comment: Suppressed by adjacent trees.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	6 m	2 m	1	150 mm	Semi-mature	No		N/A	23-Nov-19	Poor
Observations	Root		Stem		Branch			Leaf/Bud		
	No visual defects		Old pruning wounds		Damage / wounding Major dead wood			Small / sparse		
Work	Category		Action		Priority					
	Fell		Fell to ground level		3 Months					

General Tree Assessment (Detailed)

Tree ID: 32	Norway Maple <i>Acer platanoides</i>	Tag: 453 TPO:	Assessor: Maria Diez-Alonso Date: 23-May-18
--------------------	---	------------------	--

Survey Comment: Invasive cable brace installed at 5m from ground level, 2m above union. Wrong location of cable brace (it should be at 2/3 of the distance between the union and the top of the tree). Unions are tensile forks, of them with reactive wood forming a cup shape (low risk of failure).

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	15 m	6 m	1	440 mm	Semi-mature	No		N/A	23-Nov-19	Good
Observations	Root		Stem		Branch			Leaf/Bud		
	No visual defects		Multi stemmed		Damage / wounding Minor dead wood Major dead wood Old pruning wounds			Normal		
Work	Category		Action		Priority					
	Remove		Major dead wood		3 Months					

Tree ID: 33	London Plane <i>Platanus x hispanica</i>	Tag: TPO:	Assessor: Maria Diez-Alonso Date: 23-May-18
--------------------	---	--------------	--

Survey Comment: Heavily reduced on road side. Large bark wound on lowest limb over road - remove limb. Trifurcated at 7m (tensile forks). Raise canopy over roses (west side). Road site lifted from root expansion. TM required.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	25 m	12 m	1	1600 mm	Mature			N/A	23-Nov-19	Good
Observations	Root		Stem		Branch			Leaf/Bud		
	No visual defects		Trifurcated		Damage / wounding Minor dead wood Old pruning wounds			Normal		
Work	Category		Action		Priority					
	Further inspection		Massaria inspection		3 Months					
	Raise low canopy		To 5m		3 Months					
	Remove		See Comment		3 Months					

General Tree Assessment (Detailed)

Tree ID: 34 Small-Leafed Lime *Tilia cordata* **Tag:** 626 **Assessor:** Maria Diez-Alonso
TPO: **Date:** 23-May-18

Survey Comment: Remove epicormic growths up to main fork/bifurcation. Unable to assess bifurcation - assess bifurcation when doing works.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	20 m	6 m	1	460 mm	Semi-mature	No		N/A	23-Nov-19	Good
Observations	Root			Stem		Branch		Leaf/Bud		
	No visual defects			Leaning Epicormic growths Bifurcated		Minor dead wood Major dead wood		Normal		
Work	Category			Action					Priority	
	Further inspection			Climb and inspect					3 Months	
	Remove			Epicormic growths					3 Months	
				Major dead wood					3 Months	

Tree ID: 35 Swedish Whitebeam *Sorbus intermedia* **Tag:** **Assessor:** Maria Diez-Alonso
TPO: **Date:** 23-May-18

Survey Comment:

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	5 m		1	50 mm	Young	No		N/A	23-Nov-19	Good
Observations	Root			Stem		Branch		Leaf/Bud		
	No visual defects			Old pruning wounds		Old pruning wounds		Normal		
Work	Category			Action					Priority	
	No action			No action						

General Tree Assessment (Detailed)

Tree ID: 36	Common Beech <i>Fagus sylvatica</i>	Tag:	Assessor: Maria Diez-Alonso							
		TPO:	Date: 23-May-18							
Survey Comment: Monitor tree vitality. Poor pruning.										
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	5 m		1	50 mm	Young	No		N/A	23-Nov-19	Fair
Observations	Root	Stem				Branch		Leaf/Bud		
	No visual defects	No visual defect Stubs				Minor dead wood		25% dead / absent		
Work	Category	Action				Priority				
	See Comment	Unspecified								

Tree ID: 37	Wild Cherry <i>Prunus avium</i>	Tag:	Assessor: Maria Diez-Alonso							
		TPO:	Date: 23-May-18							
Survey Comment: Unstable, root plate movement, apical die back.										
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	6 m	1 m	1	80 mm	Young	No		N/A	23-Nov-19	Fair
Observations	Root	Stem				Branch		Leaf/Bud		
		Bark wounds Old pruning wounds				Apical die back Minor dead wood		25% dead / absent		
Work	Category	Action				Priority				
	Fell	Fell to ground level				3 Months				

Tree ID: 38	Silver Birch <i>Betula pendula</i>	Tag:	Assessor: Maria Diez-Alonso							
		TPO:	Date: 23-May-18							
Survey Comment:										
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	5 m	1 m	1	50 mm	Young	No		N/A	23-Nov-19	Good
Observations	Root	Stem				Branch		Leaf/Bud		
	No visual defects	Old pruning wounds				Minor dead wood		Normal		
Work	Category	Action				Priority				
	No action	No action								

General Tree Assessment (Detailed)

Tree ID: 39	Paper Birch <i>Betula papyrifera</i>	Tag:	Assessor: Maria Diez-Alonso							
		TPO:	Date: 23-May-18							
Survey Comment: Raise canopy to 2m over garden, cut back branches growing through fence.										
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	5 m	1 m	1	50 mm	Young	No		N/A	23-Nov-19	Good
Observations	Root		Stem		Branch			Leaf/Bud		
	No visual defects		Old pruning wounds		No visual defects			Normal		
Work	Category		Action		Priority					
	See Comment		See Comment		1 year					

Tree ID: 40	Swedish Whitebeam <i>Sorbus intermedia</i>	Tag:	Assessor: Maria Diez-Alonso							
		TPO:	Date: 23-May-18							
Survey Comment:										
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	5 m	1 m	1	60 mm	Young	No		N/A	23-Nov-19	Good
Observations	Root		Stem		Branch			Leaf/Bud		
	No visual defects		Old pruning wounds		Minor dead wood			Normal		
Work	Category		Action		Priority					
	No action		No action							

Tree ID: 41	Cappadocian Maple <i>Acer cappadocicum</i>	Tag:	Assessor: Maria Diez-Alonso							
		TPO:	Date: 23-May-18							
Survey Comment:										
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	4 m	1 m	1	70 mm	Young	No		N/A	23-Nov-19	Good
Observations	Root		Stem		Branch			Leaf/Bud		
	No visual defects		Old pruning wounds		Old pruning wounds			Normal		
Work	Category		Action		Priority					
	No action		No action							

General Tree Assessment (Detailed)

Report selection criteria.

Projects.

Tree Condition Survey 2018

--->
---> 1 year
---> 3 Years
---> 1 Month
---> 3 Months
---> 6 Months

Date Range.

Any Date

Work types.

----> Cut back growth :: Unspecified
----> Fell :: Fell to ground level
----> Further inspection :: Climb and inspect
----> Further inspection :: Massaria inspection
----> Ivy :: Sever/remove up to 1.5m from ground level
----> No action :: No action
----> Prune :: Unspecified
----> Raise low canopy :: To 5.5m
----> Raise low canopy :: To 5m
----> Reduce crown(s) :: To previous pruning points
----> Re-inspect :: See Comment
----> Remove :: Epicormic growths
----> Remove :: Major dead wood
----> Remove :: See Comment
----> Remove :: Sucker Growth
----> Remove :: Unspecified
----> See Comment :: See Comment
----> See Comment :: Unspecified

Latest Survey.

All surveys for the selected trees.
---> Last survey for each selected tree.

Work Completed.

---> Work Completed
---> Work Not Completed

Number of trees in selected Project(s) 41

Number of trees in Report selection 41