

| Application No: | Consultees Name: | Received: | Comment: | Response: |
|------------------------|-------------------------|---------------------|-----------------|--|
| 2018/3264/P | Barbara Brend | 28/08/2018 15:18:45 | OBJ | <p>Protest</p> <ol style="list-style-type: none">1. Box gutter has no drain. Would take water from 150 roof over 148 hall and kitchen. There is a small drain on the uphill side of 150 roof, which clearly not adequate.2. Shared gate post is reduced to half width--would destabilise. Flat cap will look unsymmetrical3. No information about parapets to flat roofs adjacent to 148 |
