



Area prior to build



Internal view after wall built showing original paving minimally disturbed.





Trenches for wall were cut as narrow as possible to minimise disturbance.  
Also note condition of surrounding grass. Only hand tools used no machinery to dig.