






Aproximate area of brickwork requiring the joints to be repointed/pressure filled



Replace missing flashing

KEY TO REPAIRS

-  Remove brickwork repair/replace outer and inner lintels
-  Areas of repointing shown hatched
-  Areas of brickwork to be replaced outlined in solid red line
-  Possible further investigation with a view to repair/replace outer and inner lintels as necessary

3rd Floor (14890mm)

North →

2nd Floor (10400mm)

1st Floor (7150mm)

Mezz Floor (4150mm)

D 14 Nov. 2017 Removal of brick arch to windows W2.13 & W2.14 omitted.
C 08 July 2017 Key to repair added.
B 19 June 2017 Lintel repair replacement highlighted.
A 11 May 2017 Repairs and repointing noted.

Kingsway Residential Limited
42 Kingsway Opening-up of Brickwork

Rear (East) Elevation

1:50 @ A1 GA-200 D

DAVID SPARROW
ARCHITECT
CHARTERED ARCHITECT
Althelstan, Long Lane
Henninggate
Rickmansworth
Hertfordshire WD3 5BT
T 01738 177025
dave@thedcloud.com
@thedcloud.com