

Application No:	Consultees Name:	Received:	Comment:	Response:
2018/5789/T	Dr Clare Halsted	14/12/2018 12:50:45	COMNOT	<p>From the documents supplied to me there is no evidence provided that my tree is causing damage. The engineering report states this: "Cause of Damage it is my opinion that the cause of damage results from clay shrinkage subsidence brought about by the action of roots from the tree located in the public footpath to the right of the property. Recommendations It is recommended that the street tree located in the side path and close to the property is removed to mitigate against further movement." In the Arboricultural Assessment Report it puts "No" for T2 (tree at no 46) roots implicated and "Yes" for T5 roots (tree in road nearer the house in question) As there are no useful documents attached to this application it is difficult for most others to understand the situation. On the basis of the information provided so far I object to this application.</p>

Total: 13