

project no 897	sheet no REP002_5DMS
date 22.11.2017	by RK

project name - sheet title

St Giles - Zone 3 - Visual Structural Inspection of No5 Denmark Street




Significant cracking to masonry around window openings

Figure 9 - Rear Elevation

project no 897	sheet no REP002_5DMS
date 22.11.2017	by RK

project name - sheet title  
St Giles - Zone 3 - Visual Structural Inspection of No5 Denmark Street



Roof top additions

Visible movement of parapet line and masonry wall below

Figure 10 - Flank Wall To No4 Denmark Street

project no 897	sheet no REP002_5DMS
date 22.11.2017	by RK

project name - sheet title

St Giles - Zone 3 - Visual Structural Inspection of No5 Denmark Street



Cracking to corners of doorway

Flank wall bowing significantly towards No6 Denmark Street

Wall line leaning away from flank wall

Figure 11 - Flank Wall To No6 Denmark Street

project no  
897

sheet no  
REP002\_5DMS

engenuiti

date  
22.11.2017

by  
RK

project name - sheet title

St Giles - Zone 3 - Visual Structural Inspection of No5 Denmark Street



Movement to masonry walls and remedial strapping

Masonry walls do not align with walls below - no visible transfer/supporting structure to underside of ceiling below