

24 CHURCH ROW PHOTOGRAPHS

to accompany

Listed Building Consent Application

Heritage Impact Assessment and Schedule of Works



Fig. 2.2A *Over-boarded ceiling, pre-2017 works*



Fig. 2.2B *Removal of over-boarding, revealing mould growth and water damage to original lime plaster and lath ceiling*



Fig. 2.2C *Water damage and failing lime plaster ceiling*



Fig. 2.2D *Frail and water damaged lathing [Note laths also set tightly together]*



Fig. 2.2E *Lathing with loose lime plaster removed*



Fig. 3.1A Existing basement entrance door, external view



Fig. 3.1B Existing basement entrance door, internal view



Fig. 3.3A *Proposed burglar alarm location*



Fig. 4.1A *Existing boundary*



Fig. 4.2A *Rear of house showing basement lightwell*



Fig. 4.3A *Existing rear lightwell, unprotected edge*