

1. Aerial view with labels



2. Street view of all properties




4. Cracking to stucco to front - 1 Agar Grove




3. Front elevation – 1 Agar Grove



5. Cracking to front corner – 1 Agar Grove





7. Rear elevation – 1 Agar Grove; note high level distortion up to side extension



9. Close-up of crack in photo 8






11. Close-up of crack in photo 10



13. Crack to staircase side extension – 1 Agar Grove



16. Cracking to front corner – 3 Agar Grove



15. Crack to front stucco – 3 Agar Grove



17. Rear elevation – 3 Agar Grove; note high level distortion up to side extension








19. Front elevation – 5 Agar Grove



21. Rear elevation – 5 Agar Grove





23. Internal crack to first floor front wall – 5 Agar Grove



25. Lime tree to Gairloch House land to west of 1 Agar Grove



26. Similar view as photo 25 except street view image from 2008




28. Cracking to concrete pathway – 1 Agar Grove




27. Crack to front boundary wall – 1 Agar Grove



29. Surface water gully – 3 Agar Grove








31. Blocked surface water gully – 1 Agar Grove



33. View of vegetation to rear of 1 Agar Grove



36. Garden wall between rear of 1 and 3 Agar Grove




35. View of vegetation and collapsed garden wall to rear of 5 Agar Grove



37. Garden wall between rear of 1 and 3 Agar Grove







39. Collapsed garden wall to 5 Agar Grove with 7 Agar Grove



41. Cracked and displaced garden wall to rear of 3 Agar Grove

