

T: +44(0) 20 7247 2462

Project No.:

508-16

: enquiries@kyson.co.uk W: www.kyson.co.uk

Drawing No.:

1502

Drawing Title:

Stripping-Out Second Floor

1:50@A1 JAN 18 ST

Drawn:

HV

Scale:

Do not scale this drawing All dimensions must be checked on site

All rights reserved. No reproduction in any material form is permitted

Walls to be retained

Parts to be stripped out

Area to be Excavated

construction programme

suit proposal levels

removed unless otherwise shown on the drawings.

All redundant services to be removed.

clean-up regimes.

Partly Demolished Structures:

Asbestos Containing Materials:

Site Condition at Completion:

Dangerous Openings:

Unforeseen Hazards:

Temporary works: Prevent debris from overloading.

Methods for safe removal, filling, etc: Submit details.

Debris: Clear away and leave the site in a tidy condition.

General: Illuminate and protect. Keep safe outside working hours.

Unauthorised persons: Prevent access.

Health Hazards:

All works to be in accordance with Conservation Specifications.

Appropriately skilled and experienced for the type of work.

for the removal of the non-original bay window.

Soil infill within crawl space to be removed

(unless stated otherwise on drawings)

throughout the construction programme

Floor finishes and floor structure to be removed