



## EOD TENDED

Drawn by Date	0 0		ω <b>π</b>	г <b>л</b> –				REV.	1	
1by JSP 26.02.2019	DRAWING NUMBER 02962L/02	:50 @ A1	ROL	CHE (EGE OND			S	DATE	27.03.2019	
Checked by Date	)ER )L/02	® A1	REPAIR DETAILS TO GROUND FLOOR	1 CHESTER PLACE REGENTS PARK LONDON NW1 4NB	info@structurehaus.com www.structurehaus.com	consulting . engineering . designing LONDON OFFICE 020 8940 7810 EXETER OFFICE 01392 363497	tructure Hau	DETAILS	ISSUED FOR TENDER	
DALP 28.02.2019	22				.com	<b>ing</b> 7810 3497	S	DRAWN	JSP	
2019	REVISION							CHECKED	DALP	

	4	
1 CHESTER PLACE  KEY PLAN	4 V 3 V	ALBANY STREET

Repair F Hack off plaster fro brickwork inspection. Allow for partial rebuild/making good of masonry and possible additional helibar to two faces as per repair A

Repair D Form helibeam bar bands from 4 no. bars in 5mm stainless steel at 225mm vertical centres fully in accordance with manufacturers instructions at each floor plate.

Repair C Install helifix bowties and bowtie HD's to floor, including noggins, fully in accordance with manufacturers instructions approx 1200mm centres.

Repair B Repair as schedule A but with external stucco/render. Make good stucco/render and decorate on completion.

Repair A Hack off plaster to full length of crack. Replace any cracked bricks using NHL 3.5 mortar in 1:2½ mix. Install helibar every third course of brick in accordance with manufacturers details and instructions. Make good plaster and finishes for completion.