



Level and Crack Monitoring

Our Ref:



Date of Issue:

11/03/2019

Provider Details

CET Property Services



Monitoring Details

Instruction Date:	08/10/2018		
Number of visits	6	Visit Frequency (Wks)	8

Visit Dates (future dates are estimated)

Setup	1	2	3	4	5	6
13/12/18	07/02/19	04/04/19	30/05/19	25/07/19	19/09/19	14/11/19

Client Details

Insurance Co.:	NIG
Client Ref:	
Client Name:	Sedgwick
Technical Mgr:	Gavin Catherine
Customer support	Tracey Horlock
Tel:	
Email:	


Risk Address

Occupier:	Removed for data protection purposes
Address:	54 Camden Square
Address:	
Town:	London
County:	
Post Code:	NW1 9XE
Contact Name	Removed for data protection purposes

Level and Crack Monitoring - Site Sketch

Our Ref: [REDACTED]

Date of Issue: 11/03/2019



TBM HILTI NAIL
IN KERB

FRONT



PROPERTY ASSURANCE
Giving our all

Level Monitoring - Reduced Levels (in metres)


Our Ref:

Date of Issue:

11/03/19

[illegible]

[illegible]





Our ref	Client ref	Client Name	Issue Date
		Sedgwick	11/03/2019

Stud locations

1	EXT front above LGF window
2	
3	
4	
5	
6	

Additional instructions / notes

Crack Monitoring - Readings

Studs nos	Align-ment	Visit Date	13/12/18	Visit Date	06/03/19	Visit Date		Visit Date		Visit Date		Visit Date	
		Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w
1	H	59.22	1.72	69.98	1.40								
1	D												
1	Check												
2	H												
2	D												
2	Check												
3	H												
3	D												
3	Check												
4	H												
4	D												
4	Check												
5	H												
5	D												
5	Check												
6	H												
6	D												
6	Check												
Caliper nos		9804		9804									
Technician		EM		EM									

Our ref	Client ref	Client Name	Issue Date
		Sedgwick	11/03/2019

Crack Monitoring - Movement Against Time

