

Application No:	Consultees Name:	Received:	Comment:	Response:
2019/4657/P	Belsize Society- Sanya Polescuk	16/11/2019 11:21:30	OBJ	Listed Buildings in Conservation Areas need to be accompanied by Heritage Statement which illustrates the understanding of reasons for the building's designation of Listed status. This application is missing such Statement. The replacement windows/doors need to illustrate by drawing the proposed locations within the thickness of walls and what, if any impact on external depths of window/door reveals. Details of the Proposed new windows/doors need to be shown in horizontal and vertical section. Details of What is proposed to happen to stained glass window sections? Factory-assembled timber windows, which show timber battens are not appropriate for historic buildings in Conservation Areas. The proposed location of new staircase seems incongruous with the historic status.
2019/4657/P	Belsize Society- Sanya Polescuk	16/11/2019 11:21:26	OBJ	Listed Buildings in Conservation Areas need to be accompanied by Heritage Statement which illustrates the understanding of reasons for the building's designation of Listed status. This application is missing such Statement. The replacement windows/doors need to illustrate by drawing the proposed locations within the thickness of walls and what, if any impact on external depths of window/door reveals. Details of the Proposed new windows/doors need to be shown in horizontal and vertical section. Details of What is proposed to happen to stained glass window sections? Factory-assembled timber windows, which show timber battens are not appropriate for historic buildings in Conservation Areas. The proposed location of new staircase seems incongruous with the historic status.
2019/4657/P	Belsize Society- Sanya Polescuk	16/11/2019 11:21:38	OBJ	Listed Buildings in Conservation Areas need to be accompanied by Heritage Statement which illustrates the understanding of reasons for the building's designation of Listed status. This application is missing such Statement. The replacement windows/doors need to illustrate by drawing the proposed locations within the thickness of walls and what, if any impact on external depths of window/door reveals. Details of the Proposed new windows/doors need to be shown in horizontal and vertical section. Details of What is proposed to happen to stained glass window sections? Factory-assembled timber windows, which show timber battens are not appropriate for historic buildings in Conservation Areas. The proposed location of new staircase seems incongruous with the historic status.
2019/4657/P	Belsize Society- Sanya Polescuk	16/11/2019 11:21:35	OBJ	Listed Buildings in Conservation Areas need to be accompanied by Heritage Statement which illustrates the understanding of reasons for the building's designation of Listed status. This application is missing such Statement. The replacement windows/doors need to illustrate by drawing the proposed locations within the thickness of walls and what, if any impact on external depths of window/door reveals. Details of the Proposed new windows/doors need to be shown in horizontal and vertical section. Details of What is proposed to happen to stained glass window sections? Factory-assembled timber windows, which show timber battens are not appropriate for historic buildings in Conservation Areas. The proposed location of new staircase seems incongruous with the historic status.