

Existing second floor windows frames overhauled and made good – as required with new draft proofing (Ventrolla or similar)

Α____

8

Sashes replaced with Histo-glass Mono acoustic glass to replicate original details



