



Site Investigation Report

Auger Ref:



Job Information	
Client	Crawford & Co
Client ref	
Visit date	12/09/2019
Report date	12/09/2019











Job Information

Overview

Brief

 $\label{lem:commissioned} \mbox{ Auger were commissioned by Crawford \& Co to undertake a site investigation within the area of concern at the property.}$

Photographs

Trial Hole 1

Fig 1.1: Trial Hole 1 Location



Fig 1.2: Trial Hole 1 Footing



Trial Hole 2

Fig 2.1: Trial Hole 2 Location



Fig 2.2 Trial Hole 2 Footing



Other Photos

Fig 7.1: Samples collected







