



Level and Crack Monitoring

Our Ref: [REDACTED] Date of Issue: 24/12/2019

Provider Details

CET Property Services - [REDACTED]

Monitoring Details

Instruction Date:	24/07/2019				
Number of visits	4	Visit Frequency (Wks)	8		

Visit Dates (future dates are estimated)

Setup	1	2	3	4	5	6
01/08/19					N/A	N/A

Client Details

Insurance Co.:	Hiscox Insurance Company
Client Ref:	[REDACTED]
Client Name:	Sedgwick
Technical Mgr:	Mike Robinson
Customer support	Samuel Barton
Tel:	[REDACTED]
Email:	

Risk Address


Occupier:	Removed for data protection purposes
Address:	63a Belsize Lane
Address:	
Town:	
County:	LONDON
Post Code:	NW3 5AU
Contact Name	Removed for data protection purposes

Level and Crack Monitoring - Site Sketch

Our Ref: [REDACTED]

Date of Issue: 24/12/2019

REAR



FRONT



**PROPERTY
ASSURANCE**
Giving our all

Level Monitoring - Reduced Levels (in metres)

Our Ref:

Date of Issue:

24/12/19

[illegible]




Level Monitoring - Movement (in millimetres)

Our Ref:

Date of Issue

24/12/19

[illegible]



	Client Name	Issue Date
	Sedgwick	24/12/2019

Stud locations

1	Rear LHS between main house and extension
2	
3	
4	
5	
6	

Additional instructions / notes

Crack Monitoring - Readings

Studs nos	Align-ment	Visit Date	01/06/19	Visit Date	19/10/19	Visit Date	23/12/19	Visit Date		Visit Date		Visit Date	
		Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w
1	H	85.34	HL	86.04	HL	83.03	0.50						
1	D												
1	Check												
2	H												
2	D												
2	Check												
3	H												
3	D												
3	Check												
4	H												
4	D												
4	Check												
5	H												
5	D												
5	Check												
6	H												
6	D												
6	Check												
Caliper nos		7539		7539		570							
Technician		AH		AH		TH							

Crack Monitoring - Movement Against Time

