



Zinc vertical cladded dormer roof recessed from frontage

Stone coping to top of parapet wall

Feature herringbone pattern brickwork to area over windows

Powder coated aluminium windows

Feature projecting stretcher brickwork to 'frame' building either side

stretcher bond facing brick slips

Feature herringbone pattern brickwork to area over windows

Powder coated aluminium windows

stretcher bond facing brick slips

Feature projecting herringbone pattern brickwork cladding to existing frame on existing facade to frame retail frontage

stretcher bond facing brick slips

Powder coated aluminium windows

Signage zone

stretcher bond facing brick slips