

Img_6111 Chamberlian Right elevation




IMG_6117 Chamberlian Side full Elevation



Img_6112 Chamberlian Left elevation



IMG_6118 Base of Party Fence Wall



IMG_6120 Base with central division



IMG_6128 Side shot of wall showing bulge



Img_6121 Temporary Support to wall