PHOTOGRAPHS OF EXISTING CHAMBERS

(as of 09 September 2019)






Fig. 1.1 Existing Bookshelf to be removed

Fig. 1.2 Existing Dado and Skirting Board

Please see Drawings 0721019/Su20, Sk22, Su21 and Sk23 for Room FR01.

PHOTOGRAPHS OF EXISTING CHAMBERS

(as of 09 September 2019)



Fig. 2.1 Elevation 01 as existing



Fig. 2.2 Existing cornice moulding



Fig. 2.3 Existing dado and skirting board




Fig. 2.4 Existing Door D02 with architrave

Please see Drawings 0721019/Su10, Sk04, Su22, Sk24 and Sk25 for Room FR02.

PHOTOGRAPHS OF EXISTING CHAMBERS

(as of 09 September 2019)








Fig. 4.1 Existing data box

Fig. 4.2 Existing freestanding bookcase to be removed

Fig. 4.3 Existing freestanding bookcase on far left to be removed

Please see Drawings 0721019/Su19 and Sk06 for Room FR04.

PHOTOGRAPHS OF EXISTING CHAMBERS

(as of 09 September 2019)



Fig. 5.1 Existing bookshelf



Fig. 5.2 Existing bookshelf detail



Fig. 5.3 Existing picture rail and cornice



Fig. 5.4 Existing dado rail



Fig. 5.5 Existing bookshelf showing retained dado rail

PHOTOGRAPHS OF EXISTING CHAMBERS

(as of 09 September 2019)







Fig. 8.1 Existing kitchenette

Fig. 8.2

Existing kitchenette doors

Fig. 8.3 Existing kitchenette cupboards

Please see Drawing 0721019/Sk18 for Room FR08.

PHOTOGRAPHS OF EXISTING CHAMBERS

(as of 09 September 2019)






Fig. 10.1 Existing WC door

Fig. 10.2 Existing WC

Please see Drawings 0721019/Su25 and Sk17 for Room FR10.

PHOTOGRAPHS OF EXISTING CHAMBERS

(as of 09 September 2019)





Fig. 11.2 External Elevation from Carey Street

Photo by: Two by Two Design Consultants

Fig. 11.3 External Elevation from Star Yard

Photo by: Two by Two Design Consultants

Fig. 11.1 External Elevation from New Square

Photo by: Two by Two Design Consultants

Butler Hegarty Architects