

PHOTO APPENDIX





IMAGE	DESCRIPTION
	Rear Elevation
	Lime trees in the rear garden
	Crack damage above the ground floor right hand window.

PHOTO APPENDIX

IMAGE	DESCRIPTION
	Crack damage on the cross wall between the bathroom and rear right hand bedroom.
	Cracking on the rear wall and ceiling line adjacent to the rear window – rear right hand bedroom