

8.0 The wall has had remedial work in the past with signs of repointing, but has continued to move over time and has cracked in places. An elevation sketch of the wall is shown below:

