



Crack Monitoring

Date of Issue: 09/09/2020

Provider Details

Monitoring Details

Instruction Date:		03/03/2020				
Number of visits		MUFN	Visit Frequency (Wks)			6
Visit Dates (future dates are estimated)						
Setup	1	2	3	4	5	6
01/06/20						

Client Details

Insurance Co.:	
Client Ref:	
Client Name:	
Technical Mgr:	
Customer support	
Tel:	
Email:	

Risk Address

Occupier:	Removed for data protection purposes
Address:	67 Abdare Gardens
Address:	
Town:	London
County:	
Post Code:	NW6 3AN
Contact Name	Removed for data protection purposes



Our ref	Client ref	Client Name	Issue Date
			09/09/2020

Stud locations

1	INT GF RHS bay window to the left
2	INT GF RHS bay window to the right
3	INT GF bay window rhs to the left
4	INT GF bay window rhs to the right
5	INT living room dining RH elevation high
6	INT living room dining RH elevation low

Additional instructions / notes

Crack Monitoring - Readings

Studs nos	Align-ment	Visit Date	01/06/20	Visit Date	13/07/20	Visit Date	09/09/20	Visit Date		Visit Date		Visit Date	
		Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w
1	H	60.72	HL	60.68	HL	60.78	HL						
1	D												
1	V												
2	V	64.65	HL	64.79	HL	65.01	HL						
2	V												
2	D												
3	H	65.39	1.33	65.41	1.34	67.50	3.40						
3	D												
3	Check												
4	D	64.30	0.94	64.33	1.07	65.77	3.06						
4	V												
4	Check												
5	H	51.04	HL	50.92	HL	50.91	HL						
5	D												
5	Check												
6	H	62.31	0.94	62.19	0.82	62.31	1.01						
6	D												
6	Check												
Caliper nos		1370		8758		6386							
Technician		RB		AJ		RM							









7	INT living/dining room LH elevation high
8	INT living/dining room LH elevation low
9	EXT LHS bay low
10	EXT LHS bay high
11	EXT middle of bay window below
12	

Studs nos	Align-ment	Visit Date	01/06/20	Visit Date	13/07/20	Visit Date	09/09/20	Visit Date		Visit Date		Visit Date	
		Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w
7	H	69.78	3.02	68.86	3.37	70.93	4.61						
7	D												
7	Check												
8	H	61.79	2.53	61.99	2.62	62.62	3.60						
8	D												
8	Check												
9	H	101.94	hi	101.70	HL	101.94	HL						
9	D												
9	Check												
10	H	73.14	hi	72.77	HL	73.18	0.98						
10	D												
10	Check												
11	H	96.29	hi	98.08	HL	96.53	HL						
11	D												
11	Check												
12	H												
12	D												
12	Check												
Calliper nos :		1370		6758		6386							
Technician :		RB		AJ		RM							

Our ref	Client ref	Client Name	Issue Date
			09/09/2020

Crack Monitoring - Movement Against Time



Our ref	Client ref	Client Name	Issue Date
			09/09/2020

Crack Monitoring - Movement Against Time

