


SECOND FLOOR - RM 2-17



SECOND FLOOR - RM 2-17



SECOND FLOOR - RM 2-18




SECOND FLOOR - RM 2-18



SECOND FLOOR - RM 2-18




SECOND FLOOR - RM 2-19



SECOND FLOOR - RM 2-19



SECOND FLOOR - RM 2-22




SECOND FLOOR - RM 2-22



SECOND FLOOR - RM 2-22




SECOND FLOOR - RM 2-23



SECOND FLOOR - RM 2-23




SECOND FLOOR - RM 2-20



SECOND FLOOR - RM 2-20




SECOND FLOOR - RM 2-21




SECOND FLOOR - RM 2-21




SECOND FLOOR - RM 2-15




SECOND FLOOR - RM 2-15



SECOND FLOOR - RM 2-15




SECOND FLOOR - RM 2-13



SECOND FLOOR - RM 2-13




FIRST FLOOR - *Post-fire photographic survey post fire.*



Photographic survey - Area covered in First Floor




FIRST FLOOR - RM 1-08




FIRST FLOOR - RM 1-08



FIRST FLOOR - RM 1-09




FIRST FLOOR - RM 1-09



FIRST FLOOR - RM 1-09



FIRST FLOOR - RM 1-10




FIRST FLOOR - RM 1-10



FIRST FLOOR - RM 1-10




FIRST FLOOR - RM 1-10 WC



FIRST FLOOR - RM 1-10 WC



FIRST FLOOR - RM 1-11




FIRST FLOOR - RM 1-11



FIRST FLOOR - RM 1-11



FIRST FLOOR - RM 1-12



FIRST FLOOR - RM 1-12



FIRST FLOOR - RM 1-12




FIRST FLOOR - RM 1-12



FIRST FLOOR - RM 1-12




FIRST FLOOR - RM 1-13



FIRST FLOOR - RM 1-13



FIRST FLOOR - RM 1-14




FIRST FLOOR - RM 1-14



FIRST FLOOR - RM 1-14




FIRST FLOOR - RM 1-14



FIRST FLOOR - RM 1-14



FIRST FLOOR - RM 1-15



FIRST FLOOR - RM 1-15



FIRST FLOOR - RM 1-15

