





## hazard: outline method statement


Interior minor dust hazards, removal of doorway infill using hand tools only to preserve lime plaster surrounding opening

refinishing of bath requires potential off-site removal note size and weight requires careful Risk Assessment and temporary protection for stairway walls and balustrade. On-site repolishing preferrable if possible to mitigate risk to operatives and historic fabric.

Ensure no active decay is visible following intensive cleaning, use of fungicide to hstoric fabric requires preparation of RA in relation to PPE and ventilation.










arts lettres techniques ARCHITECTArts Lettres Techniques Limited 2020copyright is retained ©33A ARLINGTON ROADLONDON NW1 7ES T: (020) 7383 4778architect@artslettres.comALL DIMENSIONS MUST BE VERIFED ON SITEPROJECT23 Gloucester CrescentNUMBER GC 112SCALE1:20 @ A1SUBJECTBathroom Joinery plan/elevations existingREVISIONDATE25/08/20

revisions

## elevation B







bath side (WC)

## elevation C

