

hazard: outline method statement

Door  
Existing solid flush door removed - frame  
to be retained in situ, decayed bottom threshold  
to be replaced using FSC certified European oak

Door fabricated offsite using FSC accredited  
European hardwood refitted to frame - draught  
stripping added to frame, ensure use of router  
by experienced joiner, Risk Assessment to  
cover operation.

