


KEY:

2. Planning - Level 01 Roof - Scope of works



1. Planning - Upper roof scope of works

Roof notes:

KEY:

Full survey required to roof - strip off existing tiles, put to one side those in good condition for re use, Structural Engineer to determine soundness of existing rafters and allow for replacement of 50% off existing rafters and all new battens and

Slate replacement roof tiles with, replacement roof underlay felt and battens/counterbattens to exisiting timber roof construction.

Coping Stones (Coping details / Party walls):
The coping stones are generally in poor condition and are attributing to the moisture ingress into the building. All coping stones to be removed, cleaned down and rebedded, with the appropriate lead strapping and cloaking. An allowance should be made for the replacement of any demand coping stones. made for the replacement of any damaged coping stones.

Areas of pointing is in poor condition. Patch repoint areas of poor and failing pointing. A full inspection will be required to ascertain the quantity but Condition survey has allowed for a provisional quantity of 1m² per wall.

Slates to be from one quarry to match exisiting roof as closely as possible - matching samples to be utilised. Where possible, slates from existing roof to be removed and retained for use in patching existing roofs not due for entire replacement or used in concentrated areas on replacement tile roofs.

3no. dormer roofs are of a mineral felt finish. Visually this appears to be in poor condition, with some evidence of ingress internally. Reommended that intrusive survey carried out to ascertain whether moisture has penetrated the cap sheet. If whole scale repairs are required, it is envisaged that the felt system will need to be replaced with a lead system to match the remaining units and to a line with heritage

Lead covered dormer windows.

Leadwork appears to generally be in satisfactory order however there are failed and damaged flashing details prevalent through out. Renew leadwork to damaged sections. This should be subject to a further more detailed investigation and condition survey has allowed a provisional quantity of 0.5m² per unit. It may be considered beneficial to renewal all lead flashing and soaker details, whilst access to the roof is available. An extra over cost should be sought for this.

Lead gutters and flashings
The gutters appear to be a source of moisture penetration and should be overhauled. It was noted that some remedial works have been undertaken with a liquid system. Strip out all gutters and reline with suitably dressed coded lead in accordance with the

Sheet Association guidance. Inspection by qualified contractor to verify state of existing and how much material and underlay can be retained, re used and patched. Existing code 5 lead gutters and

flashings to brought back to acceptable standards to Lead Association typical details. Tiled and pitched roof coverings should be in accordance with the relevant Building

The principal British Standards relevant to this drawing are: • BS 5534 Code of Practice for slating (including shingles). (BS 5534 should be read

in conjunction with BS 8000-6). • BS 8000-6 Workmanship on building sites. Code of Practice for slating and tiling of roofs and claddings.

• BS 5250 Control of condensation in buildings.

Many rainwater outlets were missing leaf guards and exhibited a build up of detritus.

Rainwater goods should be cleared, replaced where necessary (with cast iron to match existing) and leaf guards installed to all outlets.

Survey revealed that rooflights are beyond refurbishment and should be replaced like for like. New kerbs installed to punched opening to lift the level of existing rooflights ready for new roof level of proposed green roof. Replace all waterproof junctions as part of roof recovering.

General degradation of flaunching and pots. Allow for stripping off and resetting chimney pots on suitable flaunching.

Refer to NBS specifications 20-50-30/185 Reinforced bitumen membrane warm roof covering system 40-40-45/125 Semi Extensive green roof system 20-50-95/160 Natural stone slate roofing system 20-50-50/130 Lead sheet fully supported roof covering system

20-50-95/199 Roofing edges and junctions systems

P02 (P1) Planning Submission 22.09.2020 AM GO P01 (S3) Pre planning application issue for client sign approval 21.07.2020 KW HT 07/16/20

T +44(0)117 9299146 E bristol@ahr.co.uk

Birkbeck University of London Gordon Square, London

Planning - Roof Level - Scope of Work

This drawing is copyright and remains the property of AHR.

computer file
C:\Revit Projects\BRK-AHR-GS-XX-M3-A-Central_amie.mccabe.rvt 2019.00916.000 As indicated@A BRK-AHR-GS-RF-DR-A-27-051

This drawing is to be read in conjunction with all related drawings. All dimensions must be checked and verified on site before commencing any work or producing shop drawings. The originator should be notified immediately of any discrepancy.