



| Job Ref: | Koko H&A | Job No.: | ODP289 | Contractor: | CDG | |
|--------------------------|-------------------------------------|-------------|--------|--------------|------------|--|
| Submittal Ref: | ODP 289-SC-SAM Façade paint removal | | | Revision: | | |
| Submittal Title: | Façade Paint Removal | | | Date Issued: | 17/09/2020 | |
| Issued To: | AHA (cc) OD Project Team | | | | | |
| Spec Compliant: | Yes | | | | | |
| Critical to Procurement: | Yes | | | | | |

| Location of Sample for Approval: 1st Floor and ground floor façade. |
|---|
| Description of Sample for Approval: Paint removal samples |

Sample Submittal Sheet



1st floor sample panel

Doff cleaning system with Paint RID paint softener.

Sample Submittal Sheet





Ground floor sample.

Doff cleaning system with Paint RID paint softener.

Response Required by: Vania Ramos

| Response By: | | Date: | |
|--------------|---------------------|---------------------------------|--------------------|
| Status: | А | B | С |
| | Proceed no Comments | Proceed Subject Comments | Rejected Re Submit |

Sample Submittal Sheet



| Comments: | | | | | |
|---|--|--|--|--|--|
| | | | | | |
| Attached Doff Cleaning system information and Paint RID paint softener system. | | | | | |
| - As per specification by Artemis conservation LTD paint stripping samples issued in March 2020. | | | | | |
| The cutting of nails and then painting over, might be a problem as they might start to gain rust due to the water content on the façade and cause more damage with the new paint application. Please ensure to remove any M&E / wiring carefully and fully with the least damage the masonry as possible. | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |