

PLANNING

The contractor must check dimensions on site. Only figured dimensions to be worked from.

Any discrepancies must be reported to the architect before proceeding.


This drawing is © copyright Platform 5 Architects llp

EXISTING MATERIALS KEY

Existing roof tiles

NOTES:

- Double glazed PVC conservatory roof to be removed
- 3 Polycarbonate roof to be removed
- 4 London stock brickwork
- Painted white timber framed double glazed windows and door to conservatory side extension to be removed
- Painted white timber framed double glazed sash windows to be replaced with new
- Slate tiled roof to be removed
- Painted timber boards



94 Hanbury Street London E1 5JL

architects

33 Estelle Road

March 2020

19-104

Existing Section AA

035

e info@platform5architects.com w www.platform5architects.com

1:100

P5

1:50