

Close ups showing degradation of existing fibreglass canopy:

