



20 GAINSBOROUGH AVENUE, CANVEY ISLAND, ESSEX, SS8 7LT Tel. 07594 596518 info@enviroflowservices.co.uk



**Project** 

**Project Name:** PATRICK PARSONS

**Project Date:** 07/04/2020

Inspection Standard: MSCC4 Sewers & Drainage GB (SRM4 Scoring)

Ver: 1.2019.7.5 PATRICK PARSONS







20 GAINSBOROUGH AVENUE, CANVEY ISLAND, ESSEX, SS8 7LT Tel. 07594 596518 info@enviroflowservices.co.uk

# **Table of Contents**

Project Name	Project Number	Project Date
PATRICK PARSONS	-	07/04/2020

Project Information	P-1
Scoring Summary	P-2
Section: 1; 0141 > BOUNDARY (0141X)	1

T-1 PATRICK PARSONS







20 GAINSBOROUGH AVENUE, CANVEY ISLAND, ESSEX, SS8 7LT Tel. 07594 596518 info@enviroflowservices.co.uk

# **Project Information**

Project NameProject NumberProject DatePATRICK PARSONS07/04/2020

Client

Company: PATRICK PARSONS

**Site** 

Street: 146 CAMDEN STREET

Town or City: CAMDEN County: LONDON Post Code: NW1 9PF

Contractor

Company: ENVIROFLOW SERVICES LTD

Contact: ANDY O'RAWE

**Street:** 20 GAINSBOROUGH AVENUE **Town or City:** CANVEY ISLAND, ESSEX, SS8 7LT

**Phone:** 07594 596518 **Mobile:** 07835111497

**Email:** info@enviroflowservices.co.uk

PATRICK PARSONS P-1







20 GAINSBOROUGH AVENUE, CANVEY ISLAND, ESSEX, SS8 7LT Tel. 07594 596518

info@enviroflowservices.co.uk

# **Scoring Summary**

Project Name	Project Number	Project Date
PATRICK PARSONS		07/04/2020

#### **Structural Defects**

Section **PLR** Grade Description

All inspected pipes are in an acceptable structural condition (< grade 3).

# **Service / Operational Condition**

Section **PLR** Grade Description

All inspected pipes are in an acceptable service condition (< grade 3).

# **Abandoned Surveys**

Section **PLR Description** 

All inspections complete, none are abandoned.

### Information

These scoring summaries are based on the SRM grading from the WRc.

P-2 PATRICK PARSONS





working in partnership with



20 GAINSBOROUGH AVENUE, CANVEY ISLAND, ESSEX, SS8 7LT Tel. 07594 596518

info@enviroflowservices.co.uk


# Section Inspection - 08/04/2020 - 0141X

Section	Inspection	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
1	1	08/04/20	22:20	Not Specified	No Rain Or Snow	No	0141X
Ope	rator	Veh	icle	Camera	Preset Length	Legal Status	Alternative ID
L	_F	Not Sp	ecified	Not Specified	Not Specified	Public Sewer	Not Specified

	mopoution birodiom	Downstream	Upstream Node:	0141
140-146 Camden Street	Inspected Length:	54.00 m	<b>Upstream Pipe Depth:</b>	
Road	Total Length:	54.00 m	Downstream Node:	BOUNDARY
	Joint Length:	0.00 m	Downstream Pipe Depth:	
Combined		Pipe Shape:	Circular	_
Gravity drain/sewer		Dia/Height:	2,134 mm	
		Pipe Material:	Brick	
No flow control		Lining Type:	No Lining	
Sample survey to determine asset condition		Lining Material:	No Lining	
	Road  Combined  Gravity drain/sewer  No flow control	Road  Total Length:  Joint Length:  Combined  Gravity drain/sewer  No flow control	Road  Total Length: 54.00 m  Joint Length: 0.00 m  Combined  Gravity drain/sewer  Pipe Shape: Dia/Height: Pipe Material: Lining Type:	Road  Total Length: 54.00 m  Joint Length: 0.00 m  Combined  Gravity drain/sewer  Pipe Shape: Circular  Dia/Height: 2,134 mm  Pipe Material: Brick  No flow control  Lining Type: No Lining

Comments: Recommendations:

Depth: m





WL @ 0.01 m



DEE @ 0.01 m



JN @ 21.80 m



JN @ 28.00 m



VR @ 28.00 m

PATRICK PARSONS

(PAST SITE BOUNDARY)







20 GAINSBOROUGH AVENUE, CANVEY ISLAND, ESSEX, SS8 7LT Tel. 07594 596518

info@enviroflowservices.co.uk

# Section Inspection - 08/04/2020 - 0141X

Section	Inspection	Date	Time	Client's Job Ref	Weather	Pre Cleaned	PLR
1	1	08/04/20	22:20	Not Specified	No Rain Or Snow	No	0141X
Ope	rator	Veh	icle	Camera	Preset Length	Legal Status	Alternative ID
l L	.F	Not Sp	ecified	Not Specified	Not Specified	Public Sewer	Not Specified








JN @ 49.90 m

JN @ 53.90 m

REM @ 54.00 m

Construction Features					Miscellaneous Features				
	Structural Defects				Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	e SER No. Def SER Peak SER Mean SER Total SER (				SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

PATRICK PARSONS









20 GAINSBOROUGH AVENUE, CANVEY ISLAND, ESSEX, SS8 7LT Tel. 07594 596518

info@enviroflowservices.co.uk

# Section Pictures - 08/04/2020 - 0141X

Section	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
1	Downstream	0141X		



1, 00:00:25, 0.01 m Water level, 15% of the vertical dimension, FLOWING



2, 00:01:46, 0.01 m Attached deposits, encrustation from 7 o'clock to 5 o'clock, 5% cross-sectional area loss, LIGHT PATCHES THROUGHOUT SEWER (SUGGESTS SLIGHT INFILTRATION SEEPAGE)



3, 00:03:36, 21.80 m Junction at 3 o'clock, diameter: 150mm



4, 00:04:48, 28.00 m Junction at 9 o'clock, diameter: 150mm

PATRICK PARSONS









20 GAINSBOROUGH AVENUE, CANVEY ISLAND, ESSEX, SS8 7LT Tel. 07594 596518 info@enviroflowservices.co.uk

## Section Pictures - 08/04/2020 - 0141X

Section	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
1	Downstream	0141X		



5, 00:05:02, 28.00 m Vermin, rat, RAT SITTING IN CONNECTION



6, 00:06:48, 49.90 m Junction at 3 o'clock, diameter: 150mm



7, 00:07:45, 53.90 m Junction at 9 o'clock, diameter: 375mm



8, 00:08:06, 54.00 m General remark, PIPE OPEN UP & DIVERTS INTO DUEL SEWERS (APPROX. 1200MM DIA EACH)

PATRICK PARSONS