



Ref	Facing Material	Image	Details	Status
3	Roof standing seam zinc	 <p>Taken in the open air.</p>  <p>Taken inside the office which has a full glazed roof.</p>	<p>Standing seam zinc VMZINC 'PIGMENTO rouge/red'</p>	Details submitted

