# St Pancras Commercial Centre 63Pratt Street London NW1 oDQ

# Document Title: Asbestos and Demolition Survey

**Document number: Jo26352** 

**Revision: Co2** 

JFH Project Reference: 20004

Revision	Date	Author	Checked by	Approved by	Revision Details
C02	08/12/2020	TRAC Associates Limited	Jamie Fitzpatrick Project Manager	Jamie Fitzpatrick Project Manager	Issued for Information
Signature				Jamie Fitzpatric	6



# **Demolition Survey**

St Pancras Commercial Centre 63 Pratt Street London NW1 0DQ



### **TRAC Associates Limited**

Suite M New Maxdov House 130 Bury New Road Prestwich Manchester M25 0AA

Email: projects@trac-associates.com

Tel: 0161 641 8150



Page 1 of 77 J026352

# Contents:



1. Executive Summary [Conclusions and actions]

Issue Date: 7 Dec 2020

- 2. Project Particulars
- 3. Introduction Purpose, Aims and Objectives
- 4. Desk Top Review and Survey Planning
- 5. Survey Method
- 6. Exclusions and Caveats
- 7. Sampling and Analysis
- 8. Survey Results Interpretation
- 9. Recommendations

Appendix 1 - Conclusions

Appendix 2 - Survey Data Sheet

Appendix 3 - Areas Surveyed

Appendix 4 - Analysis Certificates

Appendix 5 - Plans

Appendix 6 - Scope of Work / Desktop Information

Page 2 of 77

# 1.0 Executive summary:



The following Asbestos Containing Materials (ACMs) have been identified during the Demolition Survey and are categorised by risk in accordance with Material Assessments carried out in line with HSE Guidance note HSG 264 Asbestos: The Survey Guide. Material Assessment Algorithm can be found in section 8 of this report:

### HIGH RISK MATERIALS - SCORES 10+

Building	Floor	Room	Item	Material	Risk assessment Score	Recommendations
There were no results found.						

### MEDIUM RISK MATERIALS - SCORES 7-9

Building	Floor	Room	Item	Material	Risk assessment Score	Recommendations
There were no results found.						

### LOW & VERY LOW RISK MATERIALS - SCORES 1-6

Building	Floor	Room	Item	Material	Risk assessment Score	Recommendations
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01	Bitumen type material	Well Bound Material	VERY LOW (4)	Remove in accordance with CAR 2012
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01	Textured coating	Textured Coating	LOW (5)	Remove in accordance with CAR 2012
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01	Textured coating	Textured Coating	VERY LOW (4)	Remove in accordance with CAR 2012
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01	Textured coating	Textured Coating	VERY LOW (4)	Remove in accordance with CAR 2012
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01	Damp proof course within brickwork	Well Bound Material	VERY LOW (3)	Remove in accordance with CAR 2012

Page 3 of 77 J026352

Issue Date: 7 Dec 2020

Issued By: Catherine Urhegyi

Building	Floor	Room	Item	Material	Risk assessment Score	Recommendations
St Pancras Commercial Centre	Ground	Unit 2 ground and mezzanine G05	Mastic drainer pad	Well Bound Material	VERY LOW (3)	Remove in accordance with CAR 2012
St Pancras Commercial Centre	Ground	Units 11,12, ground and mezzanine G06	Textured coating	Textured Coating	VERY LOW (4)	Remove in accordance with CAR 2012
St Pancras Commercial Centre	Ground	Units 11,12, ground and mezzanine G06	Bitumen- type material	Well Bound Material	LOW (5)	Remove in accordance with CAR 2012
St Pancras Commercial Centre	External	External units 1-6 E01	Cement	Asbestos Cement	VERY LOW (4)	Remove in accordance with CAR 2012
St Pancras Commercial Centre	External	External units 7- 12 E03	Cement	Asbestos Cement	VERY LOW (4)	Remove in accordance with CAR 2012

Page 4 of 77 J026352

# 1.0 Executive summary:



### **AREAS OF NO ACCESS**

Areas which have not been accessed should be presumed to contain asbestos until proven otherwise.

Issue Date: 7 Dec 2020

Building	Floor	Room/Area	Description	Recommendation
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01	No access into live electrics.	Inspection Required

Please Note: Internal areas of Unit 1 and 3 have not been surveyed as they are still occupied. They will require surveying when they become vacant.

Page 5 of 77 J026352

# 2.0 Project Particulars:



Name and address of site:	St Pancras Commercial Centre, 63 Pratt Street, London			
Name and address of client:	John F Hunt Ltd Environmental Division	John F Hunt Ltd Environmental Division, London Road, Grays, Essex		
Client contact:	Sam Hamilton			
Type of survey:	Demolition Survey (with MA only)			
Date of survey:	10 Nov 2020			
Report Revision Number:	1			
Job number:	J026352			
Lead surveyor[s]:	Steve Heard	Signature:	Q C	
Technically reviewed by:	Catherine Urhegyi	Signature:	C. Uninensi	
Report issue date:	7 Dec 2020	•		

Page 6 of 77 J026352

# 3.0 Introduction/Objectives:

Issue Date: 7 Dec 2020



TRAC Associates Limited received instruction to carry out a Demolition Survey from John F Hunt Ltd Environmental Division. This instruction has been accepted on the basis of our quotation and our terms and conditions of business.

The Demolition survey was carried out at the following site:

St Pancras Commercial Centre 63 Pratt Street London NW1 0DQ

The survey was carried out by Steve Heard.

This Demolition survey was carried out in accordance with documented in-house technical procedures procedures, in line with the requirements of HSE Guidance document HSG 264: Asbestos: The Survey Guide.

### **Purpose of Survey**

The survey was carried out in accordance with our documented in-house technical procedures, which are based on HSE Guidance note HSG 264.

HSG 264 has been prepared by the Health and Safety Executive to help people carrying out asbestos surveys and those with specific responsibilities for managing the risks from asbestos in non-domestic premises under regulation 4 of the Control of Asbestos Regulations 2012 (CAR 2012). It is also designed to provide guidance in situations where surveys may be carried out for other purposes, eg for 'managing' asbestos in domestic premises under wider health and safety legislation and for meeting the requirements of the Construction (Design and Management) Regulations 2015 (CDM). It complements and supports other guidance on managing asbestos.

The purpose of the survey was to identify, so far as is reasonably practicable, the location, extent, product type and composition of ACMs within the site, that could otherwise be potentially disturbed by the proposed demolition works.

### **Aim of Survey**

In relation to the scope of the proposed Demolition works at the site, the aim of the survey was to:

- 1. Locate and record the location, extent, and product type as far as reasonably practicable of known or presumed ACM's.
- 2. Inspect and record information on the accessibility, condition and surface treatment of know or presumed ACM's
- 3. Determine and record the asbestos type based on sampling or by making a presumption based on product type and appearance
- 4. Identify if asbestos remedial works maybe required as part of the demolition works.

Page 7 of 77 J026352

# 4.0 Desk Top Review and Survey Planning:

Issue Date: 7 Dec 2020



A desktop review and plan was carried out by TRAC Associates Limited based on available information provided by the client, relating to the survey requirements for the following site:

St Pancras Commercial Centre 63 Pratt Street London

NW1 0DQ

The survey plan considered the following:

- The scope and extent of areas to be included in the survey.
- Agreed start and completion dates
- Any areas to be excluded.
- The type of survey
- Any possible or known ACMs at the site
- The survey procedure (eg how it will be conducted) and sampling strategy
- The material assessment method and the parameters to be assessed.
- The information to be recorded and the method and format to be used.
- The quality assurance checks and procedures to be undertaken.
- Any known area where access will not be possible.
- Site safety procedures and requirements.

The survey was carried out to all areas referenced in Appendix 3.

Page 8 of 77 J026352

# 5.0 Survey Method



This survey has been undertaken in accordance with the following:

HSE Guidance document HSG 264 Asbestos: The Survey Guide

Issue Date: 7 Dec 2020

- TRAC Associates Limited in-house documented procedures
- Project risk assessments and method statements.

The Demolition survey has been carried out to locate and record the extent, as far as reasonably practicable, ACMs that may be otherwise disturbed by the proposed works. The investigations may have involve destructive inspections, as necessary, to gain access to areas to determine if ACMs may be present to areas of the site that maybe affected by the proposed demolition works.

The survey has been carried out in so far as was reasonably practical, to gather information on the nature, extent and condition of suspect ACMs. Where suspect ACMs were encountered a Material Assessment was made. The survey was carried out in a methodical and systematic manner to all areas include in the agreed scope of works, where safe and reasonable access could be made.

Page 9 of 77 J026352

# **6.0 Limitations:**



This document should not be used as a bill of quantities or to scope and specify asbestos remedial works.

Specific agreed restrictions that have been imposed on the scope and extent of the survey have been confirmed with the client prior to the commencement of site works. The specific survey requirements, scope of works and exclusions are detailed within our agreed client quotation / project plan document.

The Demolition Asbestos Survey has been carried out to attempt to locate all ACMs within the buildings surveyed (or relevant part), as far as reasonably practicable.

Specific areas of no access that have been encountered during inspections are recorded with the executive summary of this report, Appendix 1 - Conclusions and Appendix 2 - Survey Data Sheets. All areas or items that have not been accessed during the survey should be presumed to contain asbestos until proven otherwise.

Page 10 of 77 J026352

# 7.0 Sampling and Analysis:



The method for analysis of samples is in accordance with HSG 248 Asbestos: The analysts guide for sampling, analysis and clearance procedures; Appendix 2: Asbestos in bulk samples: Sampling and identification by polarised light microscopy (PLM).

Any sampling during the survey has been carried in accordance with HSE Guidance notes HSG 264 and HSG 248 and our in-house technical procedures.

All samples taken during this survey have been analysed by a laboratory holding UKAS accreditation to ISO 17025.

All relevant certificates of laboratory analysis are provided in Appendix 4.

Page 11 of 77 J026352

### Issue Date: 7 Dec 2020

# 8.0 Survey Results - Interpretation:



### **Survey Results**

The results of the survey inspections and sampling undertaken are recorded on the enclosed Survey Data Sheets (Appendix 2), Conclusions (Appendix 1) and Non-Asbestos Material Register (Appendix 3). Where asbestos containing material have been identified or presumed to be present then a Material Assessment Algorithm has been calculated as detailed in HSG 264.

In the material assessment process, the main factors influencing fibre release are given a score which can then be added together to obtain a material assessment rating. The four main parameters which determine the amount of fibre released from an ACM when subject to disturbance are:

- Product type;
- Extent of damage or deterioration;
- Surface treatment;
- Asbestos type

For the 4 parameteres listed above each are assigned a value which when added together gives a total score between 0 - 12. The score risk banded as shown in the table below:

### **Material Risk Assessment Score**

Risk Category	Risk	Score Range	Fibre release potential
Α	HIGH	10 and above	High risk with a high potential to release fibres if disturbed
В	MEDIUM	Between 7 and 9	Medium risk with a medium potential to release fibres if disturbed
С	LOW	Between 5 and 6	Low risk with and having low potential to release fibres if disturbed
D	VERY LOW	4 and below	Very low risk with very low potential to release fibres if disturbed

The scores for each parameter are derived from the risk assessment score parameter as shown in the table below:

Page 12 of 77 J026352

# 8.0 Survey Results - Interpretation (cont):

Issue Date: 7 Dec 2020



### **Material Risk Assessment Algorithm**

Product type [or debris from product]

Score	Examples of scores
1	Asbestos reinforced composites [plastics, resins, mastics, roofing felts, vinyl floor tiles, semi- rigid paint, decorative finishes and asbestos cement etc]
2	Asbestos insulating board, mill boards, other low-density boards, textiles, gaskets, ropes and woven materials and asbestos paper.
3	Thermal insulation [e.g. pipe and boiler lagging], sprayed asbestos, loose asbestos, asbestos mattresses and packing.

### Extent of damage/deterioration

Score	Examples of scores
0	Good condition: no visible damage
1	Low damage: a few scratches or surface marks, broken edges on boards or tiles, etc.
2	Moderate damage: significant breakage of materials or several small areas where material has been damaged exposing fibrous edges.
3	High damage or deterioration of materials, sprays and thermal insulation. Visible asbestos contamination by debris or residues.

### Surface treatment

Score	Examples of scores
0	Composite materials containing asbestos, reinforced plastics, resins, vinyl tiles
1	Enclosed sprays or insulation, AIB [with exposed face encapsulated], cement sheets, etc.
2	Unsealed AIB, encapsulated insulation and sprays.
3	Unsealed insulation and sprays.

Asbestos Type

Score	Examples of scores
1	Chrysotile
2	Amphibole asbestos (excluding Crocidolite)
3	Crocidolite

Page 13 of 77 J026352

### 9.0 Recommendations:



To comply with the Control of Asbestos Regulations 2012 (CAR 2012) and the Construction (Design and Management) Regulations 2007 (CDM), the dutyholder should implement the recommendations as found in the Conclusions in Appendix 1.

Where asbestos remedial works have been recommended, it is advised that the dutyholder procures the works based on a written scope of works / technical specification. Depending on the nature of the works the dutyholder should consider obtaining independent and impartial advice as to how the works should be carried out before issuing instructions.

The various recommendations given within the Asbestos Register report are explained below:

Issue Date: 7 Dec 2020

Remove or Encapsulate - If an item is recommended for removal or encapsulation it has either sustained damage and is posing an increased risk in its current condition; or due to its location it is considered high risk as it could easily be disturbed by the proposed works. Materials recommended for removal will be given one of the following recommendations:

- Removal or Encapsulation by Licensed Asbestos Removal Contractor (LARC). This will include remedial works to AIB, Insulation, and Spray Coatings and is likely to be subject to a 14 day notification to the HSE, (as per the Control of Asbestos Regulations 2012).
- Removal or Encapsulation by a Competent Contractor. This will include remedial of lower risk materials such as Asbestos Cement, Bitumen Products, Reinforced Composites, and Floor Tiles etc. Some such works may be considered Notifiable Non-Licensed Works. The Control of Asbestos Regulations 2012 does not necessarily require such removal works to be undertaken by a licensed contractor. However it is good practice, and we would strongly recommended that all removal works are undertaken by a licensed contractor.

**Restrict Access -** Materials have been identified that are in a damaged condition often with associated debris that can be easily disturbed. As such access to the area should be prevented to all persons until such a time when the area has been deemed safe for reoccupation. This will usually be once removal works have been completed.

No Access - Inspection Required

Access to the given location was either not possible at all or only limited access was possible. In both instances there is the potential for unidentified asbestos being present and as such the area must be treated as containing asbestos until full access is possible. Arrangements should be made at the earliest opportunity to revisit locations where access was not possible or access was limited in order that such areas can be inspected fully.

Items and materials that are presumed to contain asbestos will also be given the recommendation of 'No Access – Inspection required'. In these instances the item or material should be treated as containing asbestos until arrangements can be made to access such items or materials in order to carry out an inspection or sample to confirm or otherwise the presence of asbestos.

No Recommendation Required - Asbestos has not been identified and as such no further action is required

Page 14 of 77 J026352

# Appendix 1 - Conclusions

Issue Date: 7 Dec 2020



Building	Floor	Location /Room	Item No	S,P,SP,AS Sample No	Product Type	Condition	Surface Treatment	Asbestos Type	Quantity	Accessibility	Material Score	Recommendation	Additional Comments
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01, Bitumen type material	2	S DH004735	Well Bound Material	Low Damage	1	Chrysotile	22m	Usually inaccessible or unlikely to be disturbed	4	Remove in accordance with CAR 2012	N/A
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01, No access into live electrics.	3	P Visual	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Inspect Prior to Disturbance	Inspect when isolated.
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01, Textured coating to ceiling near former staircase and wc.	5	S DH004737	Textured Coating	Medium Damage	1	Chrysotile	6m²	Usually inaccessible or unlikely to be disturbed	5	Remove in accordance with CAR 2012	N/A
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01, Textured coating to ceiling in former stairwell and wc.	6	S DH004738	Textured Coating	Low Damage	1	Chrysotile	6m²	Usually inaccessible or unlikely to be disturbed	4	Remove in accordance with CAR 2012	N/A
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01, Textured coating to ceiling in former stairwell and wc.	7	S DH004739	Textured Coating	Low Damage	1	Chrysotile	6m²	Usually inaccessible or unlikely to be disturbed	4	Remove in accordance with CAR 2012	N/A
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01, Damp proof course within brickwork	41	S DH004768	Well Bound Material	Low Damage	0	Chrysotile	160m	Usually inaccessible or unlikely to be disturbed	3	Remove in accordance with CAR 2012	N/A
St Pancras Commercial Centre	Ground	Unit 2 ground and mezzanine G05, Mastic drainer pad	29	S DH004761	Well Bound Material	Low Damage	0	Chrysotile	1no.	Usually inaccessible or unlikely to be disturbed	3	Remove in accordance with CAR 2012	N/A
St Pancras Commercial Centre	Ground	Units 11,12, ground and mezzanine G06, Textured coating to ceilings at entrances and in wc's.	44	SP As DH004739	Textured Coating	Low Damage	1	Chrysotile	10m²	Usually inaccessible or unlikely to be disturbed	4	Remove in accordance with CAR 2012	N/A
St Pancras Commercial Centre	Ground	Units 11,12, ground and mezzanine G06, Bitumen- type material	45	S DH004770	Well Bound Material	Low Damage	2	Chrysotile	8m	Usually inaccessible or unlikely to be disturbed	5	Remove in accordance with CAR 2012	N/A
St Pancras Commercial Centre	External	External units 1-6 E01, Cement roof covering to all units 1-6	8	S DH004740	Asbestos Cement	Low Damage	1	Chrysotile	1500m²	Usually inaccessible or unlikely to be disturbed	4	Remove in accordance with CAR 2012	N/A

KEY:

 $S-Sampled, P-Presumed, SP-Strongly\ Presumed,\ AS-Cross\ reference\ to\ former\ sample$ 

Page 15 of 77 J026352

# Appendix 1 - Conclusions (cont)



Building	Floor	Location /Room	Item No	S,P,SP,AS	Product Type	Condition	Surface Treatment	Asbestos Type	Quantity	Accessibility	Material Score	Recommendation	Additional Comments
				Sample No									
St Pancras Commercial Centre	1	External units 7-12 E03, Cement to external roof units 7-12	40	S DH004767	Asbestos Cement	Low Damage	1	Chrysotile	1100m²	Usually inaccessible or unlikely to be disturbed	4	Remove in accordance with CAR 2012	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 16 of 77 J026352

# Appendix 2 – Survey Data Sheets

Issue Date: 7 Dec 2020



Service Type	Demolition Survey						
Report Revision Number	1	Surveyors	Steve Heard				
TEAMS Job Number	J026352	Survey Date	10 Nov 2020 to 16 Nov 2020				
Site Address:	St Pancras Commercial Centre 63 Pratt Street	Bulk Analysis Laboratory	Manchester				
London NW1 0DQ		Sample Analysis Date	19 Nov 2020 - 24 Nov 2020				

Page 17 of 77 J026352

### Survey Data Sheets





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01

Item	Quantity
No access into live electrics.	N/A

Item Number / Sample No (S,SP,P,As)	
3 / Visual (P)	

Analysis Product Type		Surface Treatment	Condition	Accessibility				
N/A	N/A	N/A	N/A	N/A				
Material Risk Score								
N/A								

Material Risk Score	
Recommendation	Inspection Required
Comment	Inspect when isolated.

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 18 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
<b>Demolition Survey</b>	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01

Item	Quantity
Floor tile and adhesive in electrical cupboard.	1m²

Item Number / Sample No (S,SP,P,As)	
1 / DH004734 (S)	

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 19 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01

Item	Quantity
Bitumen type material	22m

Item Number / Sample No (S,SP,P,As)	
2 / DH004735 (S)	

	Analysis	Product Type	Surface Treatment	Condition	Accessibility
	Chrysotile (1)	Well Bound Material (1)	1	Low Damage (1)	Usually inaccessible or unlikely to be disturbed
ı	Material Risk Score				
	4			-	

Material Risk Score	
Recommendation	Remove in accordance with CAR 2012
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 20 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01

Item	Quantity
Textured coating to ceiling in former stairwell and wc.	6m²

Item Number / Sample No (S,SP,P,As)	
4 / DH004736 (S)	

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 21 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01

Item	Quantity
Textured coating to ceiling near former staircase and wc.	6m²

Item Number / Sample No (S,SP,P,As)	
5 / DH004737 (S)	

Analysis	Product Type	Surface Treatment	Condition	Accessibility
Chrysotile (1)	Textured Coating (1)	1	Medium Damage (2)	Usually inaccessible or unlikely to be disturbed
Material Risk Score				
5				

Material Risk Score	
Recommendation Remove in accordance with CAR 2012	
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 22 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01

Item	Quantity
Textured coating to ceiling in former stairwell and wc.	6m²

Item Number / Sample No (S,SP,P,As)
6 / DH004738 (S)

A	Analysis	Product Type	Surface Treatment	Condition	Accessibility
(	Chrysotile (1)	Textured Coating (1)	1	Low Damage (1)	Usually inaccessible or unlikely to be disturbed
1	Material Risk Score				
4	1			-	

Material Risk Score		
Recommendation	Remove in accordance with CAR 2012	
Comment	N/A	

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 23 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01

Item	Quantity
Textured coating to ceiling in former stairwell and wc.	6m²

Item Number / Sample No (S,SP,P,As)
7 / DH004739 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
Chrysotile (1)	Textured Coating (1)	1	Low Damage (1)	Usually inaccessible or unlikely to be disturbed
Material Risk Score				
4			-	

Material Risk Score	
Recommendation	Remove in accordance with CAR 2012
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 24 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01

Item	Quantity
Supalux panels to stanchions within metal	12m

Item Number / Sample No (S,SP,P,As)	
39 / As DH004766 (SP)	

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 25 of 77 J026352





Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01

Item	Quantity
Damp proof course within brickwork	160m

Item Number / Sample No (S,SP,P,As)	
41 / DH004768 (S)	

Analysis	Product Type	Surface Treatment	Condition	Accessibility
Chrysotile (1)	Well Bound Material (1)	0	Low Damage (1)	Usually inaccessible or unlikely to be disturbed
Material Risk Score				
3			-	

Material Risk Score	
Recommendation	Remove in accordance with CAR 2012
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 26 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
<b>Demolition Survey</b>	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Units 7,8,9,10. G01

Item	Quantity
Brake shoe to lift	1no.

Item Number / Sample No (S,SP,P,As)	
46 / DH004771 (S)	

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 27 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Unit 5, Ground/mezzanine floors G02

Item	Quantity
Textured coating to ceiling in stairwell, kitchen and wc.	7m²

Item Number / Sample No (S,SP,P,As)	
9 / DH004741 (S)	

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				_

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 28 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Unit 5, Ground/mezzanine floors G02

Item	Quantity
Floor tile and adhesive	4m²

Item Number / Sample No (S,SP,P,As)

10 / DH004742 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				_

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 29 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

# Survey Type Demolition Survey

Building	Floor	Room
St Pancras Commercial Centre		Unit 5, Ground/mezzanine floors G02

Item	Quantity
Floor tiles and adhesive	10m²

Item Number / Sample No (S,SP,P,As)
11 / DH004743 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 30 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

# Survey Type Demolition Survey

Building	Floor	Room
St Pancras Commercial Centre		Unit 5, Ground/mezzanine floors G02

Item	Quantity
Floor tiles and adhesive	10m <sup>2</sup>

Item Number / Sample No (S,SP,P,As)

12 / As DH004743 (SP)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 31 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre		Unit 5, Ground/mezzanine floors G02

Item	Quantity
Supalux panels to stanchions within metal	21m

Item Number / Sample No (S,SP,P,As)	
38 / DH004766 (S)	

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 32 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

# Survey Type Demolition Survey

Building	Floor	Room
St Pancras Commercial Centre	Ground	Unit 6 ground and mezzanine G03

Item	Quantity
Mastic to metal flue	0.25m

Item Number / Sample No (S,SP,P,As)
18 / DH004750 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				_

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 33 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Unit 6 ground and mezzanine G03

Item	Quantity
Textured coating to ceiling in stairwell and wc	8m²

Item Number / Sample No (S,SP,P,As)
19 / DH004751 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility	
No Asbestos Detected	N/A	N/A	N/A	N/A	
Material Risk Score					
N/A					

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 34 of 77 J026352





Survey Date:	Lead Surveyor	
10 Nov 2020 to 16 Nov 2020	Steve Heard	

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Unit 6 ground and mezzanine G03

Item	Quantity
Beige floor tiles and adhesive to entrance and cupboard.	5m²

Item Number / Sample No (S,SP,P,As)
20 / DH004752 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility	
No Asbestos Detected	N/A	N/A	N/A	N/A	
Material Risk Score					
N/A					

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 35 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

# Survey Type Demolition Survey

Building	Floor	Room
St Pancras Commercial Centre	Ground	Unit 6 ground and mezzanine G03

Item	Quantity
Blue floor tile and adhesive in wc	2m²

Item Number / Sample No (S,SP,P,As)
21 / DH004753 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				_

Material Risk Score	
Recommendation	No further action required
Comment	N/A

#### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 36 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

# Survey Type Demolition Survey

Building	Floor	Room
St Pancras Commercial Centre	Ground	Unit 6 ground and mezzanine G03

Item	Quantity
Plaster mixed in rubble	2m²

Item Number / Sample No (S,SP,P,As)
22 / DH004754 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				_

Material Risk Score	
Recommendation	No further action required
Comment	N/A

#### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 37 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Unit 4 ground and mezzanine G04

Item	Quantity
Textured coating to ceiling in stairwell and wc's	8m²

Item Number / Sample No (S,SP,P,As)
27 / DH004759 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

#### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 38 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

# Survey Type Demolition Survey

Building	Floor	Room
St Pancras Commercial Centre	Ground	Unit 4 ground and mezzanine G04

Item	Quantity
Floor tile and adhesive below vinyl	6m²

Item Number / Sample No (S,SP,P,As)
28 / DH004760 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

 $S-Sampled,\,P-Presumed,\,SP-Strongly\,Presumed,\,AS-Cross\,reference\,to\,former\,sample$ 

Page 39 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Unit 4 ground and mezzanine G04

Item	Quantity
Insulation board within metal to all stanchions	54m

Item Number / Sample No (S,SP,P,As)
37 / DH004765 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

#### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 40 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

# Survey Type Demolition Survey

Building	Floor	Room
St Pancras Commercial Centre	Ground	Unit 2 ground and mezzanine G05

Item	Quantity
Mastic to metal flue	2m

Item Number / Sample No (S,SP,P,As)
31 / As DH004750 (SP)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 41 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre		Unit 2 ground and mezzanine G05

Item	Quantity
Textured coating to ceiling in stairwell and wc	7m²

Item Number / Sample No (S,SP,P,As)

33 / As DH004751 (SP)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

#### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 42 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Unit 2 ground and mezzanine G05

Item	Quantity
Beige floor tiles and adhesive, ground entrance and hall, stairs, wc and 1st landing.	14m²

Item Number / Sample No (S,SP,P,As)	
32 / As DH004752 (SP)	

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				


Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 43 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

# Survey Type Demolition Survey

Building	Floor	Room
St Pancras Commercial Centre	Ground	Unit 2 ground and mezzanine G05

Item	Quantity
Mastic drainer pad	1no.

Item Number / Sample No (S,SP,P,As)
29 / DH004761 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
Chrysotile (1)	Well Bound Material (1)	0	Low Damage (1)	Usually inaccessible or unlikely to be disturbed
Material Risk Score				
3				

Material Risk Score	
Recommendation	Remove in accordance with CAR 2012
Comment	N/A

#### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 44 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Unit 2 ground and mezzanine G05

Item	Quantity
Floor tile and adhesive under vinyl in wc	2m²

Item Number / Sample No (S,SP,P,As)	
34 / DH004763 (S)	

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				_

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 45 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

# Survey Type Demolition Survey

Building	Floor	Room
St Pancras Commercial Centre	Ground	Unit 2 ground and mezzanine G05

Item	Quantity
Supalux panels to all stanchions	60m

Item Number / Sample No (S,SP,P,As)
36 / DH004764 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

#### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 46 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Units 11,12, ground and mezzanine G06

Item	Quantity
Textured coating to ceilings at entrances and in wc's.	10m²

Item Number / Sample No (S,SP,P,As)	
44 / As DH004739 (SP)	

A	Analysis	Product Type	Surface Treatment	Condition	Accessibility
(	Chrysotile (1)	Textured Coating (1)	1	Low Damage (1)	Usually inaccessible or unlikely to be disturbed
1	Material Risk Score				
4	1			-	

Material Risk Score	
Recommendation	Remove in accordance with CAR 2012
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 47 of 77 J026352





Survey Date:	Lead Surveyor	
10 Nov 2020 to 16 Nov 2020	Steve Heard	

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	Ground	Units 11,12, ground and mezzanine G06

Item	Quantity
Adhesive under carpet to stairs, landing, entrance	12m²

Item Number / Sample No (S,SP,P,As)	
43 / DH004769 (S)	

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 48 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

# Survey Type Demolition Survey

Building	Floor	Room
St Pancras Commercial Centre		Units 11,12, ground and mezzanine G06

Item	Quantity
Bitumen- type material	8m

Item Number / Sample No (S,SP,P,As)
45 / DH004770 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
Chrysotile (1)	Well Bound Material (1)	2	Low Damage (1)	Usually inaccessible or unlikely to be disturbed
Material Risk Score				
5			-	

Material Risk Score	
Recommendation	Remove in accordance with CAR 2012
Comment	N/A

#### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 49 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	External	External units 1-6 E01

Item	Quantity
Cement roof covering to all units 1-6	1500m²

Item Number / Sample No (S,SP,P,As)	
8 / DH004740 (S)	

Analysis	Product Type	Surface Treatment	Condition	Accessibility
Chrysotile (1)	Asbestos Cement (1)	1	Low Damage (1)	Usually inaccessible or unlikely to be disturbed
Material Risk Score				
4			-	


Material Risk Score	
Recommendation	Remove in accordance with CAR 2012
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 50 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	External	External units 1-6 E01

Item	Quantity
White mastic to windows/doors	80m

Item Number / Sample No (S,SP,P,As)
23 / DH004755 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				_

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 51 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	External	External units 1-6 E01

Item	Quantity
Putty to metal windows	80m

Item Number / Sample No (S,SP,P,As)	
24 / DH004756 (S)	

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				_

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 52 of 77 J026352





Survey Date: Lead Surveyor	
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	External	External units 1-6 E01

Item	Quantity
Mastic to uPVC window frames	20m

Item Number / Sample No (S,SP,P,As)
25 / DH004757 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

#### KEY:

 $S-Sampled,\,P-Presumed,\,SP-Strongly\,Presumed,\,AS-Cross\,reference\,to\,former\,sample$ 

Page 53 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	External	External units 1-6 E01

Item	Quantity
Grey/brown mastic to brick jointing	30m

Item Number / Sample No (S,SP,P,As)
26 / DH004758 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				


Material Risk Score	
Recommendation	No further action required
Comment	N/A

#### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 54 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
<b>Demolition Survey</b>	

Building	Floor	Room
St Pancras Commercial Centre	External	External units 1-6 E01

Item	Quantity
Mastic to plastic areas of roof covering all units	180m

Item Number / Sample No (S,SP,P,As)
30 / DH004762 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 55 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
<b>Demolition Survey</b>	

Building	Floor	Room
St Pancras Commercial Centre	External	External units 7-12 E03

Item	Quantity
Grey mastic to brickwork jointing	34m

Item Number / Sample No (S,SP,P,As)	
13 / DH004745 (S)	

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				_

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 56 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	External	External units 7-12 E03

Iten	1	Quantity
Whi	te mastic to doors and windows	40m

Item Number / Sample No (S,SP,P,As)	
14 / DH004746 (S)	

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 57 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	External	External units 7-12 E03

Item	Quantity
Brown mastic to shutter surrounds Edmudsons	30m

Item Number / Sample No (S,SP,P,As)
15 / DH004747 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 58 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	External	External units 7- 12 E03

Item	Quantity
Damp proof course to doors and windows all units	15m

Item Number / Sample No (S,SP,P,As)

16 / DH004748 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 59 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
<b>Demolition Survey</b>	

Building	Floor	Room
St Pancras Commercial Centre	External	External units 7-12 E03

Item	Quantity
Damp proof course to brickwork around units	150

Item Number / Sample No (S,SP,P,As)
17 / DH004749 (S)

Analysis	Product Type	Surface Treatment	Condition	Accessibility
No Asbestos Detected	N/A	N/A	N/A	N/A
Material Risk Score				
N/A				

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 60 of 77 J026352





Survey Date:	Lead Surveyor
10 Nov 2020 to 16 Nov 2020	Steve Heard

Survey Type	
Demolition Survey	

Building	Floor	Room
St Pancras Commercial Centre	External	External units 7-12 E03

Item	Quantity
Putty to metal windows	18no.

Item Number / Sample No (S,SP,P,As)	
42 / As DH004756 (SP)	

Analysis	Product Type	Surface Treatment	Condition	Accessibility	
No Asbestos Detected	N/A	N/A	N/A	N/A	
Material Risk Score					
N/A					

Material Risk Score	
Recommendation	No further action required
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 61 of 77 J026352





Survey Date:	Lead Surveyor	
10 Nov 2020 to 16 Nov 2020	Steve Heard	

Survey Typ	е
Demolition	Survey

Building	Floor	Room
St Pancras Commercial Centre	External	External units 7-12 E03

Item	Quantity
Cement to external roof units 7-12	1100m²

Item Number / Sample No (S,SP,P,As)	
40 / DH004767 (S)	

Analysis Product Type		Surface Treatment	Condition	Accessibility
Chrysotile (1) Asbestos Cement (1)		1	Low Damage (1)	Usually inaccessible or unlikely to be disturbed
Material Risk Score				
4			-	

Material Risk Score	
Recommendation	Remove in accordance with CAR 2012
Comment	N/A

### KEY:

S – Sampled, P – Presumed, SP – Strongly Presumed, AS – Cross reference to former sample

Page 62 of 77 J026352

# Appendix 3 - Areas Surveyed

Issue Date: 7 Dec 2020



Building	Floor	Room No:	Room Type	Item
St Pancras Commercial Centre	Ground Floor	G01	Units 7,8,9,10.	Floor-concrete, vinyl, metal grid. Stair nosings-rubber. Walls-block, plasterboard, plastic, plaster, brick, concrete, metal. Panels behind electrics-wood. Ceiling-metal, plasterboard, wood, plastic, textured coating, concrete, Doors, surrounds-wood, metal. Shutters-metal. Rainwater goods-plastic. Within drilled doors/walls-foam, wood, block. Boilers in mezzanine level boiler cupboards-modern.
St Pancras Commercial Centre	Ground Floor	G02	Unit 5, Ground/mezzanine floors	Floor-carpet/vinyl on concrete/wood. Walls-plasterboard, solid. Insulation within plasterboard walls-MMMF, polystyrene, plasterboard, solid. Boiler-modern. Ceiling tiles-MMMF, plaster. Insulation on ceiling void-MMMF Ceiling in ceiling void-metal. Doors, surrounds, skirting, window frames-wood, plastic. Stair nosings-rubber. Boxing in ground ceiling void-plasterboard, wood. Stairs-wood, concrete. Tiles to wc wall-ceramic. Sink unit-modern. Ceiling-concrete. Electrics-modern.
St Pancras Commercial Centre	Ground Floor	G03	Unit 6 ground and mezzanine	Floor-carpet/wood on concrete/wood. Upstands-plasterboard. Insulation behind black wall covering-MMMF. Insulation in floor voids-MMMF. Walls-plasterboard, solid. Insulation within plasterboard walls-MMMF, polystyrene, plasterboard, solid. Boiler-modern. Ceiling tiles-MMMF, plaster, concrete. Insulation on ceiling void-MMMF. Ceiling in ceiling void-metal. Doors, surrounds, skirting, window frames-wood, plastic. Stair nosings-rubber. Stairs-concrete. Tiles to wc wall-ceramic. Sink unit-modern. Electrics-modern.
St Pancras Commercial Centre	Ground Floor	G04	Unit 4 ground and mezzanine	Floor-carpet/vinyl on concrete/wood. Ceiling above plasterboard ceiling-concrete. Firestopping-MMMF. Insulation to metal tank in cupboard-MMMF. Insulation to pipework-foam. Insulation on ceiling tiles-MMMF. Walls-plasterboard, solid, fibreboard, block. Insulation within plasterboard walls-MMMF, plasterboard, solid. Boiler-modern. Ceiling tiles-MMMF, plaster. Insulation on ceiling void-MMMF. Ceiling in ceiling void-metal. Doors, surrounds, skirting, window frames-wood, plastic. Stair nosings-rubber. Ceiling above MMMF insulation to joists and ceiling-MMMF. Stairs-wood, concrete. Tiles to wc wall-ceramic. Sink unit-modern. Ceiling-concrete. Electrics-modern.
St Pancras Commercial Centre	Ground Floor	G05	Unit 2 ground and mezzanine	Floor-carpet/vinyl on concrete/wood. Floor of mezzanine-wood. Walls-plasterboard, solid. Insulation within plasterboard walls-MMMF, plasterboard, solid. Boiler-modern. Ceiling tiles-MMMF, plaster. Insulation on ceiling void-MMMF. Ceiling in ceiling void-metal. Doors, surrounds, skirting, window frames-wood, plastic. Boxing-plasterboard, wood. Stairs-wood, concrete, metal. Tiles to wc wall-ceramic. Ceiling-concrete. Electrics-modern. Tank in cupboard-metal. Panels to plasterboard walls in shop area-wood. Boxing to beams in ceiling void-plasterboard. Secondary ceiling in ceiling void of shop-plasterboard. Insulation to pipework in ceiling void-foam. Insulation to stanchions-supalux. Heater unit-modern.
St Pancras Commercial Centre	Ground Floor	G06	Units 11,12, ground and mezzanine	Floor-carpet/vinyl/wood on concrete/wood. Walls-plasterboard, solid, wood. Insulation within plasterboard walls-MMMF, plasterboard, solid. Heater unit-modern. Ceiling tiles-MMMF, plaster. Insulation on ceiling void-MMMF. Ceiling in ceiling void-solid, wood. Doors, surrounds, skirting, window frames-wood, plastic. Stair nosings-rubber. Stairs-metal, concrete. Tiles to wc wall-ceramic. Sink unit-modern. Ceiling-concrete, metal, cement. Electrics-modern.

Page 63 of 77 J026352

# Appendix 3 - Areas Surveyed (cont)

Issue Date: 7 Dec 2020



Building	Floor	Room No:	Room Type	Item
St Pancras Commercial Centre	External	E01		Wall-metal, brick. Doors, surrounds, window frames-wood, metal, uPVC. Shutters-metal. Roof-metal, cement. Rainwater goods-plastic.
St Pancras Commercial Centre	External	E03		Wall-metal, brick. Doors, surrounds ,window frames-wood, metal, uPVC. Shutters-metal. Roof-metal, cement. Rainwater goods-plastic.

Page 64 of 77 J026352

#### Issue Date: 7 Dec 2020 Issue



# Appendix 4 – Sample Certificates

Page 65 of 77 J026352



Trac Laboratories Limited New Maxdov House 130 Bury New Road Prestwich, Manchester, M25 OAA

Tel: 0161 641 8151

E-mail: samples@trac-lab.com Web: www.trac-lab.com

Company Reg No. 10743864



Certificate Number TRAC/20/11/0089

Job Ref: J026352

	BULK SAMPLE CERTIFICATE FOR IDENTIFICATION OF ASBESTOS FIBRE								
Site Address	St Pancra 63 Pratt S London NW1 0DC				Client	John F H London F Grays Essex RM20 4D		ion	
Date Sample Rec	eived	17/11/2020		Date Sample Analysed	19/11/2020 - 24/1	1/2020	Date Approved:	07/12/2020	

### **RESULTS**

Sample Number	Client Ref Number	Sample Description	Material Type	Fibre Type Detected	Notes:
1	DH004734	Floor tile and adhesive in electrical cupboard.	Reinforced Composite	N.A.D.I.S	
2	DH004735	Bitumen type material	Well Bound Material	Chrysotile	
3	DH004736	Textured coating to ceiling in former stairwell and wc.	Textured Coating	N.A.D.I.S	
4	DH004737	Textured coating to ceiling near former staircase and wc.	Textured Coating	Chrysotile	
5	DH004738	Textured coating to ceiling in former stairwell and wc.	Textured Coating	Chrysotile	
6	DH004739	Textured coating to ceiling in former stairwell and wc.	Textured Coating	Chrysotile	

Key: CHRYSOTILE = "White Asbestos", AMOSITE = "Brown Asbestos", CROCIDOLITE = "Blue Asbestos" FIBROUS ANTHOPHYLLITE, FIBROUS TREMOLITE, FIBROUS ACTINOLITE (Rare Asbestos types), NAD (No Asbestos Detected)

### **RESULTS**

Sample Number	Client Ref Number	Sample Description	Material Type	Fibre Type Detected	Notes:
7	DH004740	Cement roof covering to all units 1-6	Asbestos Cement	Chrysotile	
8	DH004741	Textured coating to ceiling in stairwell, kitchen and wc.	Textured Coating	N.A.D.I.S	
9	DH004742	Floor tile and adhesive	Reinforced Composite + Well Bound Material	N.A.D.I.S	
10	DH004743	Floor tiles and adhesive	Reinforced Composite + Well Bound Material	N.A.D.I.S	
11	DH004745	Grey mastic to brickwork jointing	Well Bound Material	N.A.D.I.S	
12	DH004746	White mastic to doors and windows	Well Bound Material	N.A.D.I.S	
13	DH004747	Brown mastic to shutter surrounds Edmudsons	Well Bound Material	N.A.D.I.S	
14	DH004748	Damp proof course to doors and windows all units	Well Bound Material	N.A.D.I.S	
15	DH004749	Damp proof course to brickwork around units	Well Bound Material	N.A.D.I.S	
16	DH004750	Mastic to metal flue	Well Bound Material	N.A.D.I.S	
17	DH004751	Textured coating to ceiling in stairwell and wc	Textured Coating	N.A.D.I.S	
18	DH004752	Beige floor tiles and adhesive to entrance and upboard.	Reinforced Composite + Well Bound Material	N.A.D.I.S	
19	DH004753	Blue floor tile and adhesive in wc	Reinforced Composite + Well Bound Material	N.A.D.I.S	
20	DH004754	Plaster mixed in rubble	Non Asbestos Insulating Board	N.A.D.I.S	
21	DH004755	White mastic to windows/doors	Well Bound Material	N.A.D.I.S	
22	DH004756	Putty to metal windows	Well Bound Material	N.A.D.I.S	
23	DH004757	Mastic to uPVC window frames	Well Bound Material	N.A.D.I.S	
24	DH004758	Grey/brown mastic to brick jointing	Well Bound Material	N.A.D.I.S	

Key: CHRYSOTILE = "White Asbestos", AMOSITE = "Brown Asbestos", CROCIDOLITE = "Blue Asbestos" FIBROUS ANTHOPHYLLITE, FIBROUS TREMOLITE, FIBROUS ACTINOLITE (Rare Asbestos types), NAD (No Asbestos Detected)

TRAC Laboratories Limited	Doc Ref: 1	Page 67 of 77
---------------------------	------------	---------------

### **RESULTS**

Sample Number	Client Ref Number	Sample Description		Material Type	Fibre Type Detected	Notes:
25	DH004759	Textured coating to ceiling in stairwell and w	c's	Textured Coating	N.A.D.I.S	
26	DH004760	Floor tile and adhesive below vinyl		Reinforced Composite + Well Bound Material	N.A.D.I.S	
27	DH004761	Mastic drainer pad		Well Bound Material	Chrysotile	
28	DH004762	Mastic to plastic areas of roof covering all un	its	Well Bound Material	N.A.D.I.S	
29	DH004763	Floor tile and adhesive under vinyl in wc		Reinforced Composite	N.A.D.I.S	
30	DH004764	Supalux panels to all stanchions		Non Asbestos Insulating Board	N.A.D.I.S	
31	DH004765	Insulation board within metal to all stanchio	Insulation board within metal to all stanchions		N.A.D.I.S	
32	DH004766	Supalux panels to stanchions within metal		Non Asbestos Insulating Board	N.A.D.I.S	
33	DH004767	Cement to external roof units 7-12		Asbestos Cement	Chrysotile	
34	DH004768	Damp proof course within brickwork		Well Bound Material	Chrysotile	
35	DH004769	Adhesive under carpet to stairs, landing, entr	ance	Well Bound Material	N.A.D.I.S	
36	DH004770	Bitumen- type material		Well Bound Material	Chrysotile	
37	DH004771	Brake shoe to lift		Reinforced Composite	N.A.D.I.S	
Analyst Name		Analyst Signature	Authoris	er Name	Authoriser Signature	
Kane Hulse, Nassifu Lugolobi		K Hulse	Catherin	ne Urhegyi	C.C	reliensi
Comments:						

Key: CHRYSOTILE = "White Asbestos", AMOSITE = "Brown Asbestos", CROCIDOLITE = "Blue Asbestos" FIBROUS ANTHOPHYLLITE, FIBROUS TREMOLITE, FIBROUS ACTINOLITE (Rare Asbestos types), NAD (No Asbestos Detected)

TRAC Laboratories Limited	Doc Ref: 1	Page 68 of 77
---------------------------	------------	---------------

#### Method statement and Disclaimers

Samples have been analysed to determine the presence of asbestos fibres using TRAC Laboratories Ltd in-house method of polarised light microscopy coupled with dispersion staining techniques based on the HSG 248.

- I. Trace identification of asbestos fibres represents one or two fibres.
- II. The analysis samples will be stored for a minimum of 6 months.
- III. The material type reported is the opinion of the sampler primarily and confirmed by the analyst but will not form part of TRACs UKAS Accreditation.
- IV. This Certificate of Identification of asbestos fibre(s) cannot be reproduced in full unless written approval from TRAC Laboratories Ltd has been obtained.
- V. The above results only relate to the items tested.
- VI. In situations where the sample condition or size is deemed unacceptable or unsatisfactory by the analyst, the client will be notified.
- VII. TRAC Laboratories Ltd will not accept liability for the way the results are interpreted or acted upon.


Report - Demolition Survey (with MA only)

# Appendix 5 – Plans

Issue Date: 7 Dec 2020

Page 70 of 77 J026352

Please Note: Internal areas of Unit 1 and 3 have not been surveyed as they are still occupied. They will require surveying when they become vacant



TRAC Associates Limited Suite M, New Maxdov House 130 Bury New Road, Prestwich Manchester

M25 0AA

Tel. No. 0161 641 8150

Email: projects@trac-associates.com

#### Drawing key


	Asbestos cement sheet Horizontal		Asbestos cement sheet Vertical
0	Asbestos cement flue/ downpipe		Asbestos cement debris
	Asbestos cement guttering		AIB/ insulation debris
	AIB Horizontal		AIB vertical
	Insulation products		Asbestos spray coating
	Textured coating		Woven products
	Floor tiles & Linoleum		Bonded materials
	CAF gaskets	$\overline{\leftarrow}$	No access
004	Asbestos sample/'AS' sample position	004	NON Asbestos sample
1/01 W.C	Floor Room description		SCALE-FOR ICE ONLY

#### THIS IS A COLOUR DRAWING AND SHOULD NOT BE RELIED ON IF VIEWED IN **BLACK AND WHITE ONLY**

CLIENT: John F Hunt Ltd

SITE: St Pancras Commercial centre LOCATION: Ground Floor Units 1-6 SURVEY DATE: 10/11/2020

TRAC REF: J026352 SURVEYORS: Steve Heard TYPE OF SURVEY: Demolition



#### Main & Northern Office

TRAC Associates Limited
Suite M, New Maxdov House
130 Bury New Road, Prestwich
Manchester

M25 0AA

Tel. No. 0161 641 8150

Email: projects@trac-associates.com

#### Drawing key


	Asbestos cement sheet Horizontal		Asbestos cement sheet Vertical	
0	Asbestos cement flue/ downpipe		Asbestos cement debris	
	Asbestos cement guttering		AIB/ insulation debris	
	AIB Horizontal		AIB vertical	
	Insulation products		Asbestos spray coating	
	Textured coating		Woven products	
	Floor tiles & Linoleum		Bonded materials	
	CAF gaskets	$\overline{\leftarrow}$	No access	
004	Asbestos sample/'AS' sample position	004	NON Asbestos sample	
1/01 W.C	Floor Room description	NOT TO SCALE-FOR GUIDANCE ONLY		

## THIS IS A COLOUR DRAWING AND SHOULD NOT BE RELIED ON IF VIEWED IN BLACK AND WHITE ONLY

CLIENT: John F Hunt Ltd

SITE: St Pancras commercial centre LOCATION: Ground Floor Units 7-12

SURVEY DATE: 10/11/2020 TRAC REF: J026352 SURVEYORS: Steve Heard TYPE OF SURVEY: Demolition



#### Main & Northern Office

TRAC Associates Limited Suite M, New Maxdov House 130 Bury New Road, Prestwich Manchester

M25 0AA

Tel. No. 0161 641 8150

Email: projects@trac-associates.com

#### Drawing key


	Asbestos cement sheet Horizontal		Asbestos cement sheet Vertical
0	Asbestos cement flue/ downpipe		Asbestos cement debris
2000	Asbestos cement guttering		AIB/ insulation debris
	AIB Horizontal		AIB vertical
	Insulation products		Asbestos spray coating
	Textured coating		Woven products
	Floor tiles & Linoleum		Bonded materials
	CAF gaskets	$\overline{\leftarrow}$	No access
004	Asbestos sample/'AS' sample position	004	NON Asbestos sample
1/01 W.C	Floor Room description		SCALE-FOR ICE ONLY

### THIS IS A COLOUR DRAWING AND SHOULD NOT BE RELIED ON IF VIEWED IN BLACK AND WHITE ONLY

CLIENT: John F Hunt Ltd

SITE: St Pancras commercial centre LOCATION: External Units 1-6

SURVEY DATE: 10/11/2020 TRAC REF: J026352 SURVEYORS: Steve Heard TYPE OF SURVEY: Demolition



#### Main & Northern Office

TRAC Associates Limited Suite M, New Maxdov House 130 Bury New Road, Prestwich Manchester

M25 0AA

Tel. No. 0161 641 8150

Email: projects@trac-associates.com

#### Drawing key

	Asbestos cement sheet Horizontal		Asbestos cement sheet Vertical
0	Asbestos cement flue/ downpipe		Asbestos cement debris
2000	Asbestos cement guttering		AIB/ insulation debris
$\mathbb{Z}$	AIB Horizontal		AIB vertical
	Insulation products		Asbestos spray coating
	Textured coating		Woven products
	Floor tiles & Linoleum		Bonded materials
	CAF gaskets	$\overline{\leftarrow}$	No access
004	Asbestos sample/'AS' sample position	004	NON Asbestos sample
1/01 W.C	Floor Room description		SCALE-FOR ICE ONLY

## THIS IS A COLOUR DRAWING AND SHOULD NOT BE RELIED ON IF VIEWED IN BLACK AND WHITE ONLY

CLIENT: John F Hunt Ltd

SITE: St Pancras Commercial centre LOCATION: External Units 7-12 SURVEY DATE: 10/11/2020

TRAC REF: J026352 SURVEYORS: Steve Heard TYPE OF SURVEY: Demolition Issue Date: 7 Dec 2020

## Appendix 6 – Scope of Work / Desktop Information



Scope	General
Demolition Survey (with MA only)	Demolition survey Includes for: * Provision of 2 man surveying team * Survey will require 4 shifts on site to complete * Collection and analysis of samples * Provision of interpretive report * All plant and equipment required * All internal and external areas of the site
Desktop information	Details
Description and construction type (s) of the buildings included in the survey	Brick built building comprising of ground and first floor
Occupation and use of buildings included in the survey	Areas to be vacant during survey
Site access arrangements and site contact details	Access to be arranged via the client
Listed building restrictions or any other conservation restrictions	Not listed

Page 75 of 77 J026352

Desktop information	Details
History of the site in terms of former use and occupation	Educational
Underground structures (concealed footings, cellars, ducts, tunnels and undercrofts of demolished buildings etc).	Not applicable
Up to date layout plans	Provided
Available site asbestos information (Registers / Remedial information)	No previous asbestos information has been provided
Site specific hazards	None over and above standard risk assessments
Specialist access equipment (Work at height / confined spaces)	Not required
LARC required to facilitate access	Not required
Analytical monitoring requirements (reassurance or clearance air testing)	Not required
Plant and equipment requiring intrusive assessment	Visual assessment only of live plant
Labelling of ACMs	Not required

Page 76 of 77 J026352

Desktop information	Details
Age of site / buildings	Not known
Site induction required	Not confirmed
Making good requirements	Not required
Escalation protocol on discovery of significant damaged ACMs	Contact TRAC PM
Decontamination facilities	Not required
Lighting requirement	Not required
Exclusions	As per scope of works
Notes, site and safety arrangements	Not required
Hours of Work	

Page 77 of 77 J026352