



*View towards no. 26 showing crash deck scaffolding in place*



*Front view, no. 26 on right of image*



*Porch of 26 Leighton Road before erection of crash deck*



*Underside of porch entablature showing spalled render prior to opening up*





*Underside of iron flat following removal of spalled render*



*Exposed iron flat showing brickwork above*



*Exposed iron flat showing bearing to column*



*Projecting course showing moulded stonework to left and presumed concrete work to corner section, with spalled and missing render*





*Side view of porch parapet with damaged render*



*View of porch parapet with damaged render to projecting concrete work*



*Front view of porch parapet showing concrete coping*



*View from above showing asphalt roofing and unclipped flashing*