


Principal Elevation: South

roofs generally. inspect roofs, flashings, soakers, drips and leadwork generally, effecting repairs where necessary. replace tiles with clay tiles to match exactly and lead to repair details. clean gutters and match where repairs are required. refer to the conditions survey

tile hanging to all areas. inspect surfaces, flashings, drips and leadwork generally, effecting repairs where necessary. replace tiles with clay tiles to match exactly and lead to repair details. refer to the conditions survey

canopy over the main entrance. carefully reveal former layers of paint to determine the composition and colour of the original decoration. strip heavy over-painting and repaint to approved specification affect repairs as necessary to leadwork and structure. refer to conditions survey

inspect condition of rainwater goods generally throughout. repair and replace as appropriate using cast iron goods and brackets to match existing closely



DATUM 83.000

DATUM 83.000

frl roof light (flat roof) vrl velux style roof light (pitched roof) crl conservation style roof light (pitched roof) f wall / roof mounted flue to gas boiler / gas fire. terminal colour is black **abx** extract terminal as air brick, such as rytons rd4mfab, colour coded to suit brickwork frx mushroom extract terminal for flat roof prx fabricated lead pitched roof vent as extract terminal, such as provided by o'brien sheet lead fabrications ltd note: existing windows are generally timber frames with leaded glazing (single glazed) and fine painted metal sashes. some metalwork has been replaced with painted timber to mimic the original sash. on the north and the west elevations of the main house the windows are simpler with single glazing and painted timber frames. there are a pair of painted metal frame windows on the north elevation the timber casement windows found on the annexe will be replaced by low profile double glazed units with an anodised bronzed aluminum frame Existing building fabric and structure, including roofs, tiling, masonry, windows, and rainwater goods are to be maintained and repaired/refurbished where necessary. the conditions survey will form the basis from which the maintenance works will be scheduled and agreed. scheme 2 further revisions 20 existing canopy is retained. 21 existing non-original svp removed from principal facade, drainage re-routed to north elevation 22 underground cellar is retained and stabilised as directed by the structural engineer and as appropriate, and incorporated into the 23 new raised and fielded panel doors. layout and joinery detailing is based on the existing main door to the main house. 24 please note that the glass guarding fall protection to the terrace L2.06 was removed on the previously revised drawings REV B, and replaced with conventioal painted metal frames, based on the

BOWKER SADLER PARTNERSHIP LIMITED

**REV C** 15 Jan 2021 GMcG Planning Application further revised, see notes above REV B 10 Aug 2020 GMcG Revised Planning Application marked at Revision B REV A 05 Dec 2019 GMcG Original Planning Application marked at Revision A REV. DATE DRN. CHKD. ROJECT The Hoo, Scheme 2 17 Lyndhurst Gardens, Hampstead, London Returning A Grand Victorian House To Private Domestic Accc. **NW3 5NU** 

Mr and Mrs Yu REPRESENTED BY JAGA Developments (London) RAWING South and East Elevations as Proposed SCALE SHEET SIZE DRAWN CHECKED DATE 1:50 @ A0 GMcG Oct 2019 BOWKER SADLER ARCHITECTURE A: Hatherlow House, Hatherlow, Romiley, Stockport SK6 3DY T: 0161 406 7333 E: bsp@bowker-sadler.co.uk

1140

W: www.bowker-sadler.co.uk

19013

TATUS FOR PLANNING