



# **Site Investigation Report**

Auger Ref:



Job Information	
Client	Sedgwick
Client ref	
Visit date	15/10/2019
Report date	15/10/2019











## Job Information

## Overview

Auger were commissioned by Sedgwick to undertake a site investigation within the area of concern at the property.

Brief

We first attended site and completed a deep excavation to attempt to locate the foundations to the property. We were unsuccessful in doing this due to the amount of services running through the hole and the suspected depth of the foundations.

We re attended site with 2 engineers and continued to excavate down. We then were able to locate the foundation and successfully probed the underside. Below is the trial hole log showing the foundation details for the property:

## **Photographs**

## Trial Hole 1

#### Fig 1.1: Trial Hole 1 Location




Fig 1.2: Trial Hole 1 Footing



#### Other Photos

Fig 7.1: Services running through hole



