

GEOCORE
Site Investigations Ltd.



**IN PARTNERSHIP
WITH**

QG
QuestGates
Chartered Loss Adjusters
& Claims Specialists

SITE INVESTIGATION FACTUAL REPORT


NAME:




ADDRESS:

20A Merton Rise, London, NW3 3EN


CLIENT REF:





OUR REF:



QG
QuestGates
Chartered Loss Adjusters
& Claims Specialists





		<h1>SITE AND DRAINAGE LAYOUT</h1>	
Site Crew:	Sam McNiff / Harry Kelly	Date:	10th December 2020
Address:	20A Merton Rise, London, NW3 3EN		
Geocore Ref:		Client Ref:	



General Comments:

Key:	=RW Gully	=RW Pipe	=FW Gully	=W/C or S/V pipe	=Inspection Chamber
	=Rodding Eye	=Surveyed pipe indicating fall	=Unsurveyed pipe		
	=E/H=Exploratory Hole (hand dug pit and/or window sample)				
	=Hedge or Shrub	=Tree	=Boundary line		


		<h2 style="text-align: center;">FOUNDATION PIT RECORD</h2>	
Site Crew:	Sam McNiff / Harry Kelly	Date:	10th December 2020
Address:	20A Merton Rise, London, NW3 3EN		
Geocore Ref:			Client Ref:
Trial Pit No: 1			




For strata information, please refer to borehole log TPBH1.

BOREHOLE LOG RECORD

Site Crew:	Sam McNiff / Harry Kelly	Date:	10th December 2020
Address:	20A Merton Rise, London, NW3 3EN		
Geocore Ref:		Client Ref:	
Borehole No: 1			



BOREHOLE LOG




Location 20A Merton Rise, London, NW3 3EN.				BOREHOLE No TP/BH1	
Client Questgates.		Date 10-12-20	Ground Level (m)	Co-Ordinates ()	Sheet 1 of 1


SAMPLES & TESTS			Water	STRATA				Instrument
Depth	Type No	Test Result		Reduced Level	Legend	Depth (Thickness)	DESCRIPTION	
						0.05	MADE GROUND Concrete.	
						(0.95)	MADE GROUND Light brown slightly sandy, gravelly Clay with many cobbles. Gravel is of sub-angular fine to coarse brick, concrete, china, clay, glass, flint and quartz. Cobbles are sub-angular brick and concrete.	
1.20 1.20	IIV D1	60kPa @ 1.20m.				1.00	Firm becoming stiff with depth brown slightly sandy, slightly gravelly laminated CLAY. Gravel is of sub-angular fine to coarse flint, sandstone and quartz. BASE OF FOUNDATION AT 1.00m.	
1.70 1.70	IIV D2	77kPa @ 1.70m.				(2.00)		
2.20 2.20	IIV D3	90kPa @ 2.20m.						
2.70 2.70	IIV D4	90kPa @ 2.70m.				3.00		

Boring Progress and Water Observations						Chiselling			Water Added		GENERAL REMARKS
Date	Time	Depth	Casing Depth	Dia. mm	Water Dpt	From	To	Hours	From	To	
											Borehole terminated at 3.0m. Excavation remained open and dry on completion. No roots observed.

All dimensions in metres Scale 1:21.875	Client Engineer Dave Clare.	Method/ Plant Used HH Window Sampler.	Logged By S. McNiff
--	--------------------------------	---	------------------------

BOREHOLE BH 66122 GP, AUGUST 7/8K GP, 10/21

		<h2 style="text-align: center;">FOUNDATION PIT RECORD</h2>	
Site Crew:	Sam McNiff / Harry Kelly	Date:	10th December 2020
Address:	20A Merton Rise, London, NW3 3EN		
Geocore Ref:			Client Ref:
Trial Pit No: 2			



For strata information, please refer to borehole log TPBH2.



GEOCORE
Soil Investigation Limited

BOREHOLE LOG

AGS


Location 20A Merton Rise, London, NW3 3EN.			BOREHOLE No TP/BH2	
Date 10-12-20	Ground Level (m)	Co-Ordinates ()		
Client Questgates.			Sheet 1 of 1	


SAMPLES & TESTS			STRATA				
Depth	Type No	Test Result	Water	Reduced Level	Legend	Depth (Thickness)	DESCRIPTION
						(0.40) 0.40	MADE GROUND Concrete.



(BS1377 : PART 2 : 1990)


* : Liquid Limit and Plastic Limit Wet Sieved.

		<h1>SITE AND DRAINAGE LAYOUT</h1>	
Site Crew:	Sam McNiff / Harry Kelly	Date:	10th December 2020
Address:	20A Merton Rise, London, NW3 3EN		
Geocore Ref:		Client Ref:	



General Comments:

Key:	=RWGully	=RWPipe	=FWGully	=W/C or S/V pipe	=Inspection Chamber
	=Rodding Eye	=Surveyed pipe indicating fall	=Unsurveyed pipe		
	=E/H=Exploratory Hole (hand dug pit and/or window sample)				
	=Hedge or Shrub	=Tree	=Boundary line		

	SURVEY NOTES		
Site Crew:	Sam McNiff / Harry Kelly	Date:	10th December 2020
Address:	20A Merton Rise, London, NW3 3EN		
Geocode Ref:		Client Ref:	

The only drainage within 3 metres of the area of damage is RWG 1. There is also an RWP with a 68 mm plastic pipe which runs across the front of the building above ground and also discharges into RWG 1. The drain run has silt deposits within the pipe but still working. The pipe is 100mm PVC.

Runs 1 and 2 are both PVC.


The drain run upstream of I/C 1 appears to have been relined.

The interceptor trap within I/C 2 is blocked.

	RECOMMENDATIONS		
--	------------------------	--	--

The following recommendation is a maintenance issue.

Item 1: Drainage system would benefit from a high pressure water clean.


		<h2 style="text-align: center;">QUOTATION</h2>			
Site Crew:		Sam McNiff / Harry Kelly		Date:	10th December 2020
Address:		20A Merton Rise, London, NW3 3EN			
Geocode Ref:				Client Ref:	
Item	Description	No	Unit	Rate	Total
	Drainage report				
Item 1	Drainage system: High pressure water clean and CCTV				
				TOTAL	
NOTES: Half day charge			Sub Contract Value		
			Minimum Charge		
			VAT at 20%		
			Grand Total		

Internal Condition Grade (ICG)	Typical Defect Descriptions
5	<p>Already collapsed</p> <p>Deformation >10% and broken</p> <p>Extensive areas of fabric missing</p> <p>Fracture with deformation >10%</p>
4	<p>Broken</p> <p>Deformation >10% and broken</p> <p>Fracture with deformation 6-10%</p> <p>Multiple fracture</p> <p>Serious loss of level</p> <p>Serious joint defects with voids or soil visible (open joint with >50mm soil or void visible or joint displacement >25% of diameter)</p> <p>Surface damage - spalling large (entire surface of brick missing)</p> <p>Surface damage - wear large (entire surface of brick missing)</p>
3	<p>Fracture with no deformation or deformation <5%</p> <p>Longitudinal cracking with or multiple cracking</p> <p>Minor loss of level</p> <p>Severe joint defects, ie open joint (large) or displaced joint (large)</p> <p>Surface damage - spalling medium (large areas of chipped brick)</p> <p>Surface damage - wear medium (entire surface of brick missing)</p>
2	<p>Circumferential crack</p> <p>Moderate joint defects, ie open joint (medium) or displace joint (medium)</p> <p>Surface damage - spalling slight (small fragments breaking away from surface)</p> <p>Surface damage - wear slight (increased roughness)</p>
1	No or slight structural defects
Note	Deformed sewers that have subsequently been relined with a structural lining can normally be considered to have no deformation

DRAINAGE CODES			
Code	Description	Code	Description
B	Broken pipe at (or from to) o'clock	JN	Junction at o'clock, diameter mm
CC	Crack circumferential from to o'clock	JX	Junction defective at o'clock, diameter mm
CL	Crack longitudinal @ o'clock	LC	Lining of sewer changes/starts/finishes at this point
CM	Cracks multiple from to o'clock	LD	Line of sewer deviates down
CN	Connection at o'clock, diameter mm	LL	Line of sewer deviates left
CNI	Connection at o'clock, diameter mm, intrusion mm	LR	Line of sewer deviates right
CU	Camera under water	LU	Line of sewer deviates up
CX	Connection defective at o'clock	MC	Material of sewer changes at this point
D	Deformed sewer %	MH	Manhole/node
DC	Dimension of sewer changes at this point	OB	Obstruction % height/diameter loss
DE	Debris (non silt/grease) % cross-sectional loss	OJL	Open joint large
DEG	Debris grease % cross sectional area loss	OJM	Open joint medium
DES	Debris silt % cross-sectional area loss	RFJ	Roots fine (at joint)
FC	Fracture circumferential from to o'clock	RMJ	Roots mass % cross-sectional area loss (at joint)
FL	Fracture longitudinal at o'clock	RTJ	Roots tap (at joint)
FM	Fractures multiple from to o'clock	SA	Survey abandoned
GO	General observation at this point	WL	Water level % height/diameter
H	Hole in sewer at o'clock	X	Sewer collapsed % cross-sectional area loss
JDM	Joint displaced medium	FH	End of survey
JDL	Joint displaced large		



WINDOW
SAMPLING



CHAPTER 1

DOMESTIC
SUBSIDENCE
INVESTIGATIONS



CHAPTER 2


WINDOWLESS
SAMPLING



CHAPTER 3

THE HOLE STORY

CABLE
PERCUSSION
DRILLING



CHAPTER 4

ROTARY
DRILLING



CHAPTER 5

GROUND
SOURCE
DRILLING



CHAPTER 6

CCTV DRAIN
SURVEYS



CHAPTER 7