

# Hestur Limited

Photograph 7

Existing timber infill to former opening to be removed to allow treatment of damp and replaced.



Photograph 8

Wall to be removed

