

## 2038: 37 Doughty Street **Upper Ground Floor Front Room**







Upper Ground Floor front room showing evidence of damp between windows



An investigation hole undertaken to the wall showing a void between wall line and brickwork