

**01**  
**1005** **Gallery 10 Existing Roof Plan**  
**1:100**

Organic growth on wall along gutter line where there is currently no access



**02**  
**1005** **Gallery 10 South End Photograph**

Gallery 10 Covered Pitched Roof

Existing access door & gantry system

Roof gutter that requires access for maintenance



**03**  
**1005** **Gallery 10 North End Photograph**



**Notes:** 15/04/2021 12:41:36

Drawings are based on survey data and may not accurately represent what is physically present.

Do not scale from this drawing. All dimensions are to be verified on site before proceeding with the work.

All dimensions are in millimeters unless noted otherwise.

Purcell shall be notified in writing of any discrepancies.



P02	14.04.21	TM	Update to LBC information
REV	DATE	DRAWN	DESCRIPTION

CLIENT  
**The British Museum**

PROJECT  
**The British Museum Roof Repairs**

JOB NUMBER  
**241026**

PURCELL

TITLE  
**Gallery 10 Access Works**  
**Existing Plan**

SIZE	SCALE	LAST REVISED	DRAWN	CHECKED
A1L		15/04/2021	TM	TM
REV	SUITABILITY/REASON FOR ISSUE			
P02	S4 - Listed Building Consent			
DRAWING NAME				
24102600-XX-DR-A-1005				