


**Front Elevation of Lower Ground Floor, 42 Parkhill Road (see diagram 100 - 101 A)**



- In the lower ground bay, you can see the white painted plaster that will be restored to glazed timber windows more in keeping with the overall front facade design.
- Central bay window in poor repair, all to be made good.
- Lower portion of this window not visible from street level due to its placement in the front lightwell

**Rear Elevation of Lower Ground Floor, 42 Parkhill Road (see diagram 120 - 121 A)**



- Existing windows in poor repair





- Existing right hand window out of alignment with those above