



Area not surveyed



Side Passage



New timber framed window, double glazed, brickwork infill below to match existing

