

Appendix 1: Site Photographs



Photo 1: No.1 Railey Mews



Photo 2: Rear window beside the steel beam outside the first floor kitchen and dining area



Photo 3: East Wall looking south from the first floor kitchen window



Photo 4: East Wall looking south from another first floor kitchen window



Photo 5: East wall (under construction) looking west from the roof terrace



Photo 6: View looking south at application from the roof terrace




Photo 7: Obscured glazing at the rear ground floor bedroom



Photo 8: Glass roof at the rear ground floor bedroom ('main bedroom')



Photo 9: Long view of No.1 Railey Mews



Photo 10: View of the application site from Fortress Road



Photo 11: View of the application from east of Fortress Grove