

Tavistock Place - Windows

Tender: 06.10.2021

Windows in a dilapidated condition throughout, draughty, cold and warping.



Internal, secondary glazing layer remains ineffective and obstructs maintenance



Window company advises their replacement

Windows Close Up



Timber starting to rot and peel away, dilapidated throughout



Structural issues from rotting



Sliding system no longer operating smoothly due to warping

