



REV. ISSUED DESCRIPTION DRAWN CHECKED - -

PROJECT DESCRIPTION HOLBORN LINKS 20-22 SP PROPOSED THIRD FLOOR PLAN PROJECT 5 20-22 SP & 46-47 BS

PLANNING

21.865 DRAWING NO PL.1344

EDR

NOTES:

1. New external door. 2. Existing lift refurbished.

3. Existing lift refurbished.

5. New wall mounted FCUs in architectural casings.

11. Existing metal gangway retained. Existing painted metalwork redecorated KEY black.

7. New vertical board on board black cladding.

8. New decking to rear external courtyards.

12. New metal balustrade decorated black.

15. New casement window to match existing.

14. New sash window to match existing.

16. New solid surface hearth.

21. New plant screen and door.

27. New plasterboard access panel.

36. New shower provision created.

40. New guarding.

39. Existing areas of damp to be repaired.

48. Existing flat roof and coping cleaned.

49. New locker provision created within building.

screeded to receive new floor finish.

55. Existing inspection chamber retained.

54. Existing gully retained.

57. New nosings to stairs.

56. New planting.

53. Existing stairs walls repaired ready for redecoration.

59. New balustrade to match refurbished existing.

63. Existing ladder retained and redecorated.

70. New dry riser through 47 BS staircase.

61. Existing roof access ladder retained and redecorated.

66. New communications provisions created within buildings. 67. New cleaners sink and bib taps with tiled splash back. 68. Refer to structural engineers information for structural details.

43. New stair tread installed to match existing stairs.

45. Existing light well floors made good and cleaned.

46. Areas of damaged plaster repaired and re decorated.

redecorated. 20. New cycle stands.

13. All existing painted metal bars redecorated white.

17. Existing stairs refurbished with new carpet runner.

Areas of damaged lath and plaster repaired, re-plastered and redecorated.

19. Areas of damaged plaster over EML repaired, re-plastered and

22. Existing WCs fully refurbished with new sanitary wear and finishes.

25. All previous abutments made good to match existing finish locally.

28. Any existing damaged or missing areas of plasterboard with skim finish repaired and redecorated.

29. Existing cast iron fireplace and wood surround retained and refurbished. Existing decorated wood surround stripped back and redecorated.

30. New black reeded panels to back and sides of fireplace chambers. 31. New damp-proofing system installed to internal walls, membrane over boarded with dot and dab plasterboard with skim finish.

32. Existing fireplace hearth and surround retained. Existing decorated surround stripped back and redecorated.

33. All existing window boards and reveals retained, stripped back and redecorated, colour to be agreed.

37. Refer to internal elevations for details on new reveal treatment. 38. Existing painted metal railings and balustrade redecorated.

41. Existing wall behind historic service riser plastered to match existing adjacent wall finishes.

44. Existing external staircase retained, prepared and redecorated.

42. Any existing redundant service openings infilled with plasterboard with skim finish repaired and redecorated.

47. New companionway to provide access from the lower ground light well to the ground floor level.

50. New damp-proofing system installed to floor internally. Membrane over screeded to receive new floor finish.

Existing rain water goods cleaned and re decorated black. Damaged or poorly installed components to be repaired or replaced.

Existing areas of damaged plaster and beads repaired and re-plastered ready for decoration.

60. New external signage, design to be developed as part of a site wide

62. Refer to proposed roof plans for roof, mansard and gutter works.

64. Existing light well walls made good to match existing ready for decoration. 65. New planters to match timber cladding with stainless steel cable trellis system in diamond patten for climbing plants above fixed back to existing light well wall.

New concealed fire curtain to opening head, refer to internal elevations for details.

New service riser. Risers sized to allow the retention of existing features behind.

72. New service cupboard to replace exiting in the same location. 73. New condenser units, refer to MEP drawings for details.

51. New damp-proofing system installed to vault ceilings, walls and floor. Wall

34. Existing landing boxing and lobby entrance reveal retained, stripped back and redecorated.

35. Existing stone surrounds retained and cleaned. First floor surround in 20

Southampton Place front room to be repaired to remove visible historic

26. New hit and miss chimney vents installed at existing locations.

23. New metal bars installed externally to existing window to match existing. 24. New extended external stairs with cycle channel to match existing.

9. New electric radiators as indicated. 10. New wall mounted cycle stands.

4. New double doors.

6. New kitchenettes.

GENERAL PLAN NOTES

Refer to MEP drawings and information for details of proposals.

on plan is within applicants control).

Application boundary.

Existing Walls

To be retained.

New Walls New partition walls.

ground and up and slabs in lower ground floors.

Refer to structural drawings and information for details of proposals.

Floor Finishes - New floor finishes throughout over existing floor boards to

Windows - All windows to be refurbished with new ironmongery unless otherwise indicated. Refer to window and ironmongery schedules for details.

Doors - New doors indicated with an (N) after the reference. Existing doors to

be refurbished with new ironmongery. Refer to door and ironmongery schedules

Ownership Boundary Line (all other land shown south of blue line

DATE SCALE AT A1 JUNE '21 1:50 CW



