

REV. ISSUED DESCRIPTION DRAWN CHECKED A 18.10.21 External works description.

DESCRIPTION HOLBORN LINKS PROJECT 5 ELEVATION 20-22 SP & 46-47 BS EDR

DESCRIPTION DATE SCALE AT A1 46-47 BS PROPOSED REAR JULY '21 1:50 PLANNING CW

REV B

GENERAL NOTES:

roof strengthening works.

6. New wall mounted external lights.

9. New wall mounted cycle stands.

12. New external building signage. 13. New metal balustrade painted black. 14. New plant screen and door.

Southampton Place.

17. New 150mm louvre for shower and toilet. 18. New 100mm kitchenette extract wall fan. 19. New 100mm toilet extract wall fan. 20. New 100mm louvre for shower.

strengthening works or raised kerbs. 26. Existing chimney render and flashing's repaired.

27. Existing parapet and party walls repaired. 28. New extended external stairs to match existing.

32. New decking to rear external courtyards.

30. New roof access hatches.

schedules for details. 34. All existing windows refurbished.

5. New sash window.

7. New external door.

NOTES:

Outside Scope of Works

3. Existing painted metal bars redecorated white.

Grey hatch indicates adjacent buildings.

1. Existing painted metal railings and balustrade redecorated.

4. New glazing to replace exiting top panels modified for plant vent.

New mechanical equipment and service runs to roofs. Refer to MEP information for details on services and structural engineers information for

8. Existing metal gangway retained and re-supported to structural engineers details. Existing painted metalwork redecorated black.

10. New metal bars installed externally to existing window to match existing. 11. Existing rain water goods cleaned and redecorated black. Damaged or

New roof membrane overlaid onto existing asphalt roof on 22 Southampton Place and 46-47 Bloomsbury Square.

23. Existing mansard roofs retained and missing/damaged slates replaced 24. Damaged, slipped or missing slates to mansards to be replaced to match

25. New mechanical equipment located on roofs. Refer to MEP information for details on services and structural engineers information for roof

29. Condenser units in rear courtyard, refer to MEP information for details.

33. Boosted cold water service to serve bib tap, refer to MEP drawings and

31. Existing dormers leadwork, roofs and flashings to be repaired.

16. New roof membrane overlaid onto existing asphalt roof on 20-21

poorly installed components repaired and replaced.

21. New 100mm louvre for future tea point fan connection. 22. New free standing roof edge protection to flat roof perimeter.

> DRAWING NO PL.1552